FIRE SAFETY INSPECTION REPORT

UNION GARMENTS LTD.

UNION INDUSTRIAL COMPLEX, M.C BAZAR, SHISHU PALLI PLUS ROAD, MULAID, TENGRA, SREEPUR

OTHER FACTORIES: UNION KNITWEAR LTD.





SUMMARY

Union Garments Ltd. was surveyed for fire safety on 03-04-2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.



Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	The exit stairs are not separated from work areas or other spaces on each floor by firerated construction.	Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors.	Within 3 months
			If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system.	









F-2 Fire Rated Construction

Unsealed penetrations and openings are located in exit stair enclosures.

Seal all penetrations and openings in exit stair enclosure walls to maintain the fire separation.

Within 3 months





F-3 Fire Rated Construction

The EMR room is completely open to the discharge of the exit stair.

Separate the EMR room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations

Within 3 months








F-4 Fire Rated Construction

Flammable liquid storage area is not separated by fire-rated construction from exit discharge due to a non-fire-rated door.

Separate the hazardous materials / flammable liquid storage room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations.

Within 3 months







F-5 Fire Rated Construction

The boiler/generator/transfor mer room is not separated by fire-rated construction from exit discharge due to a non-fire-rated door.

Separate the boiler/generator/transformer room by a minimum 2-hr firerated construction. Seal and/or protected all openings to maintain the required fire separations

Within 3 months





F-6 Fire Rated Construction

Multiple storage areas were observed throughout building with no fire-rated separation from surrounding areas.

Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction.

Within 3 months

Where separate storage rooms are not feasible, provide defined storage areas and limit the storage arrangement as follows:

- Maximum height of 2.4m and maximum area of 23m2
- If sprinkler protected: maximum height of 3.66m and maximum area of 93m2

Separate areas of unenclosed combustible storage by a minimum clear distance of 3m.









F-7 Egress

Egress doors and gates with locking features are provided at all exit stair openings, and exit discharge.

Remove locking features from all egress doors and gates.

Immediate

If locks are required for security reasons, utilize special door locking features complying with NFPA 101.










F-8 Egress

Dustbins and other combustible storage were observed in exit stair landings.

Remove all storage from exit stairs and egress paths.

Immediate







F-9 Egress

Collapsible gates and coiling doors are provided at all exit stair openings, and exit discharge.

Replace all gates and coiling doors along the means of egress with side-hinged, swinging egress doors. Within 1 month

If locks are required for security reasons, utilize special door locking features complying with NFPA 101.









F-10 Fire Protection

The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.

Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.

Design within 4 months, install within 9 months





F-11 Fire Protection

Inspection, testing, and maintenance records for the fire alarm system were not available.

Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.

Within 3 months

Furthermore, alarm did not sound when functional test was performed.

F-12 Fire Protection

The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.

Replace the single-station smoke alarms with automatic smoke detectors tied into the fire alarm system. Configure the fire alarm system to initiate occupant notification upon activation of any two smoke detectors in addition to the manual fire alarm stations.

Within 6 months





