

FIRE SAFETY INSPECTION REPORT

BOVS APPARELS LTD.

**JAMUR ,MUCHIPARA,HEMAYETPUR SAVAR,DHAKA,
BANGLADESH**

OTHER FACTORIES: NONE



ACCORD
on Fire and Building Safety in Bangladesh

April 13, 2014

SUMMARY

Bovs Apparels Ltd. was surveyed for fire safety on 4/13/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.

Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	Diesel area is not separated by fire-rated construction in front of sub-station room.	Separate the hazardous materials / flammable liquid storage room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations.	Within 3 months
				
F-2	Fire Rated Construction	The boiler, generator and transformer rooms are not separated by fire-rated construction.	Separate the boiler, generator and transformer room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations	Within 3 months



F-3	Fire Rated Construction	Areas used for combustible storage are not separated by fire-rated construction on the ground floor.	Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction. Where separate storage rooms are not feasible, provide defined storage areas and limit the storage arrangement as follows: - Maximum height of 2.4m and maximum area of 23m² - If sprinkler protected: maximum height of 3.66m and maximum area of 93m² Separate areas of unenclosed combustible storage by a minimum clear distance of 3m.	Within 3 months
-----	-------------------------	--	---	-----------------



F-4	Fire Rated Construction	The exit stairs are not separated from work areas on each floor by fire-rated construction.	Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors.	Within 3 months
-----	-------------------------	---	--	-----------------

If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system.






F-5	Fire Rated Construction	Unsealed penetrations and openings are located in the fire-rated floor/ceiling assemblies in the southwest corner on each floor.	Provide a minimum 2-hr fire-rated shaft to separate the utility risers from each floor level.	Within 3 months
-----	-------------------------	--	---	-----------------





F-6	Egress	Egress doors and gates with locking features are provided at building exit, exit stairs and exit discharge.	Remove locking features from all egress doors / gates. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Immediate
-----	--------	---	--	-----------





F-7	Egress	Sliding doors are provided at building exits, exit stairs, along egress routes and exit discharge.	Replace all gates / sliding doors along the means of egress with side-hinged, swinging egress doors. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Within 1 month
-----	--------	--	--	----------------



F-8	Fire Protection	The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.	Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.	Design within 4 months, install within 9 months
F-9	Fire Protection	The high-rise building has an occupied floor greater than 23m (75 ft) and is not provided with automatic sprinkler protection. The large occupant loads, heavy fuel loading, and anticipated extended egress times warrant sprinkler protection.	Provide automatic sprinkler protection throughout the building in accordance with NFPA 13.	Design within 6 months, install within 12 months
F-10	Fire Protection	Inspection, testing, and maintenance for the fire alarm system was not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.	Within 3 months
F-11	Fire Protection	The fire alarm system does not appear to provide adequate audible notification coverage for the each floor.	Provide additional notification appliances such that the fire alarm system is audible throughout the building in accordance with NFPA 72.	Within 6 months



F-12	Egress Lighting	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles.	Within 3 months
F-13	Egress Lighting	Inspection, testing, and maintenance for the emergency lighting system was not in accordance with The ACCORD standard.	Inspect, test and maintain the emergency lighting system in accordance with The ACCORD standard. Keep written records on-site.	Within 3 months