FIRE SAFETY INSPECTION REPORT

NAZ KNIT WEAR LTD ANWAR PLAZA, GANAKBARI, SAVAR, DHAKA, BANGLADESH

OTHER FACTORIES: NONE





SUMMARY

Naz Knit Wear LTD was surveyed for fire safety on 4/24/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.



Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	The boiler, generator, and transformer room is not separated by firerated construction openings, non-rated doors, and penetrations.	Separate the boiler, generator, and transformer room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations	Within 3 months









F-2 Fire Rated Construction

Unsealed penetrations and openings are located in the fire-rated wall assemblies. This was located specifically (but not limited to) on the basement, ground and first floor storage rooms.

Provide a minimum 2-hr firerated shaft to separate the utility risers from each floor level.

Seal all penetrations and openings in floor/ceiling assemblies to maintain the fire separation.

Within 3 months





F-3 Fire Rated Construction

The exit stairs are not separated from work areas, and other spaces on each floor by firerated construction. This was reflected throughout the building on all floors.

Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors.

If fire doors are required to be held open for functional reasons, provide automaticclosing devices tied to the fire alarm system. Within 3 months





F-4 Egress

Egress doors / gates with locking features are provided at building exits, exit stairs, along egress routes, and exit discharge. This was reflected throughout the building, on all floors.

Remove locking features from all egress doors / gates.

Immediate

If locks are required for security reasons, utilize special door locking features complying with NFPA 101.





F-5 Egress

Collapsible gates / sliding doors are provided at building exits, exit stairs, along egress routes, and exit discharge. This was reflected throughout the building, on all floors.

Replace all gates / sliding doors along the means of egress with side-hinged, swinging egress doors.

If locks are required for security reasons, utilize special door locking features complying with NFPA 101. Within 1 month





F-6 Fire Protection The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.

Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.

Design within 4 months, install within 9 months



F-7

Fire Protection Inspection, testing, and maintenance for the fire alarm system was not in accordance with NFPA 72.

Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.

Within 3 months

F-8 Fire Protection The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.

Replace the single-station smoke alarms. Provide automatic smoke detection throughout the building in accordance with NFPA 72.

Within 6 months





F-9	Egress
	Lighting

Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes. This was reflected throughout the building, on all floors.

Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles.

Within 3 months

F-10 Egress Lighting

Inspection, testing, and maintenance records for the emergency lighting system were not available.

Inspect, test and maintain the emergency lighting system in accordance with The ACCORD standard. Keep written records on-site.

Within 3 months

