

FIRE SAFETY INSPECTION REPORT

THE SHANIN CORPORATION LTD.
12 TO 1 HOSSAIN UDDIN KHAN, 1ST LANE LALBAGH

OTHER FACTORIES: NONE



ACCORD
on Fire and Building Safety in Bangladesh

September 10, 2014

SUMMARY

The Shanin Corporation Ltd. was surveyed for fire safety on 9/10/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.

Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	The boiler, generator and transformer room is not separated by fire-rated construction (openings, non-rated doors, penetrations). They are open to a path of egress from the building.	Separate the boiler, generator and transformer room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations	Within 3 months



F-2	Fire Rated Construction	Areas used for combustible storage are not separated by fire-rated construction. Locations: All Floors	Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction. Where separate storage rooms are not feasible, provide defined storage areas and limit the storage arrangement as follows: - Maximum height of 2.4m and maximum area of 23m² - If sprinkler protected: maximum height of 3.66m and maximum area of 93m² Separate areas of unenclosed combustible storage by a minimum clear distance of 3m.	Within 3 months
-----	-------------------------	--	---	-----------------





F-3	Fire Rated Construction	Rooms used for combustible storage are not separated by fire-rated construction.	Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction.	Within 3 months
		Location: Basement		



F-4	Fire Rated Construction	The exit stairs are not separated from work areas in the basement by fire-rated construction.	Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system.	Within 3 months
-----	-------------------------	---	--	-----------------



F-5	Fire Rated Construction	Unsealed penetrations and openings are located in the fire-rated floor/ceiling assemblies.	Provide a minimum 2-hr fire-rated shaft to separate the utility risers from each floor level.	Within 3 months
-----	-------------------------	--	---	-----------------



F-6	Egress	Egress doors / gates with locking features are provided at building exits, exit stairs, along egress routes and exit discharge.	Remove locking features from all egress doors / gates. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Immediate
-----	--------	---	--	-----------





F-7	Egress	Storage was located in the egress path.	Keep egress paths and stairs clear of storage.	Immediate
-----	--------	---	--	-----------


Located on all the floors except the third floor and roof.



F-8	Egress	Storage was located in the exit stair.	Remove all storage from exit stairs and egress paths.	Immediate
-----	--------	--	---	-----------




F-9	Egress	Collapsible gates / sliding doors are provided at building exits, exit stairs, along egress routes and exit discharge.	Replace all gates / sliding doors along the means of egress with side-hinged, swinging egress doors. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Within 1 month
-----	--------	--	--	----------------



F-10	Egress	The width of egress aisles is less than 36-in.	Provide minimum aisle widths of 36-in.	Within 3 months
------	--------	--	--	-----------------

Locations:
Basement
Ground Floor
Third Floor
Roof



F-11	Egress	The day-care room is located in an exit stair. Location: Ground Floor	Relocate the day-care so it is not located in the exit stair on the ground floor with direct accesses to an exit.	Within 3 months
------	--------	---	---	-----------------



F-12	Egress	Handrails are not provided in the East exit stair.	Provide handrails on at least one side of the East exit stair.	Within 3 months
------	--------	--	--	-----------------



F-13	Egress	The East basement stair did not have adequate headroom (56 in).	Provide an adequate headroom height of 80 in. minimum from the East basement stair.	Within 3 months
------	--------	---	---	-----------------



F-14	Egress	Exit stairs from the basement discharge inside the building.	Provide 2-hr fire-rated exit passageway leading directly outside (vestibules to separate any storage areas).	Within 6 months
------	--------	--	--	-----------------



F-15	Fire Protection	The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.	Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.	Design within 4 months, install within 9 months
------	-----------------	--	--	---



F-16	Fire Protection	Inspection, testing, and maintenance of the fire alarm system is not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.	Within 3 months
------	-----------------	--	---	-----------------

F-17	Fire Protection	The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.	Remove single-station smoke alarms. Provide automatic smoke detection throughout the building, tied into the fire alarm system, in accordance with NFPA 72.	Within 6 months
------	-----------------	--	---	-----------------



F-18	Egress Lighting	Exit sign provided at a door that was not an exit.	Remove exit sign.	Immediate
		Location: Roof		



F-19	Egress Lighting	Inspection, testing, and maintenance for the emergency lighting system was not in accordance with The ACCORD standard.	Inspect, test and maintain the emergency lighting system in accordance with The ACCORD standard. Keep written records on-site.	Within 3 months
------	-----------------	--	--	-----------------

F-20	Egress Lighting	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles.	Within 3 months
------	-----------------	--	--	-----------------