

FIRE SAFETY INSPECTION REPORT

MAHADI FASHION PVT LTD.

ACCORD ID: 11996

**BASUGAON, PUBAIL, GAZIPUR SADAR, GAZIPUR
-1721**

OTHER FACTORIES: NONE.



ACCORD
on Fire and Building Safety in Bangladesh

February 7, 2015

SUMMARY



Mahadi Fashion pvt Ltd. was surveyed for fire safety on 2/7/2015 by Jensen Hughes. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.

Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe	
F-1	Fire Rated Construction	Unsealed electrical shafts are located in the fire-rated floor/ceiling assemblies at northeast corner.	Provide a minimum 2-hr fire-rated shaft to separate the utility risers from each floor level and seal all penetrations in floor/ceiling assemblies to maintain the fire separation.	Within 3 months	
					

F-2	Fire Rated Construction	Rooms used for combustible storage are not separated by fire-rated construction on the ground floor.	Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction.	Within 3 months
-----	-------------------------	--	--	-----------------



F-3	Fire Rated Construction	The empty elevator shafts does not have the proper fire rated construction on each floor.	Provide the proper 2 hr. fire rating for the shaft and 1.5 hr. fire rating for the elevator door.	Within 3 months
-----	-------------------------	---	---	-----------------





F-4	Fire Rated Construction	The exit stair enclosures are not separated from work areas on each floor by fire-rated construction.	The exit stair enclosure shall be provided with a minimum 1-hr fire resistance rating for buildings with 3 or fewer stories and a minimum of 2-hr fire resistance rating for buildings 4 or more stories. Provide minimum 1.5-hr fire rated doors for buildings that are 4 or more stories. Ensure that the fire doors are self-closing and positive latching and they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system.	Within 3 months
-----	-------------------------	---	--	-----------------





F-5	Fire Rated Construction	The northeast exit stair is not separated from maintenance room on the 2nd floor by fire-rated construction.	Provide minimum 2-hr fire-rated construction wall. Seal all unprotected openings to separate the exit stairs from other building spaces on all floor levels.	Within 3 months
-----	-------------------------	--	--	-----------------



F-6	Egress	Egress doors and gates with locking features are provided at building exits, along egress routes and exit discharge.	Remove locking features from all egress doors and gates. If locks are required for security reasons, utilize special door locking features complying with NFPA 101 and ACCORD standard 6.8.2.	Immediately
				
				
F-7	Egress	Building did not have stair designation signs and occupant load signs at required locations.	Provide stair designation signs and occupant load signs at required locations.	Immediately
F-8	Egress	Collapsible gates and sliding doors are provided at building exits, along egress routes and exit discharge.	Replace all gates and sliding doors along the means of egress with side-hinged, swinging egress doors in accordance with ACCORD standard 6.8.1.	Within 1 month




F-9 Egress

Exit stairs serve more than 5 stories and do not have required re-entry provisions.

Every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets ACCORD standard 6.8.3.1.

Within 3 months



F-10 Egress


Handrails are not provided on both sides of the exit stair.

Provide handrails on both sides of the exit stair. New handrails shall have a minimum height of 865 mm (34 in.) and a maximum height of 965 mm (38 in.) as measured from the leading edge of the tread. Intermediate handrails shall be provided when the stair width exceeds 2.2 m (87 in.)

Within 3 months



F-11	Egress	Southwest and northwest exit stairs discharge inside the building on the ground floor.	Modify stair to discharge directly outside or Provide 2-hr fire-rated exit passageway leading directly outside (vestibules to separate any storage areas).	Within 6 months
------	--------	--	--	-----------------



F-12	Fire Protection	The fire alarm system is antiquated, not a listed system and does not provide alarm and notification features consistent with acceptable standards.	Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.	Design within 4 months, install within 9 months
------	-----------------	---	--	---



F-13	Fire Protection	The required no smoking signs are not present in the factory.	Smoking is prohibited in any garment factory building or separate storage building. Signs shall be posted in Bengali and English at all building entrances. If the factory creates a designated smoking area outside the building, information of these areas will be posted on the signs.	Within 1 months
F-14	Fire Protection	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10.	Inspect, test and maintain the portable fire extinguishers and keep written records on-site, in accordance with NFPA 10.	Within 3 months
F-15	Fire Protection	Inspection, testing and maintenance for the fire alarm system is not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system and keep written records on-site, in accordance with NFPA 72.	Within 3 months

F-16	Fire Protection	Fire department connection is not provided.	Provide fire department connection in accordance with ACCORD standard 5.5.4.	Within 3 months
F-17	Fire Protection	Inspection, testing and maintenance of the fire pump system is not in accordance with NFPA 20.	Inspect, test and maintain the fire pump system and keep written records on-site, in accordance with NFPA 20.	Within 3 months
F-18	Fire Protection	Inspection, testing and maintenance of the standpipe system is not in accordance with NFPA 14.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 14.	Within 3 months
F-19	Fire Protection	Visible and audible notification was not provided for the building in accordance with NFPA 72.	Provide visible and audible notification for the building in accordance with NFPA 72.	Within 3 months
F-20	Fire Protection	Fire pump is not provided in accordance with ACCORD standard 5.5.1 and 5.5.1.1.	Provide a new fire pump that meets ACCORD standard 5.5.	Within 6 months
F-21	Fire Protection	The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.	Remove single-station smoke alarms. Provide automatic smoke detection throughout the building, tied into the fire alarm system, in accordance with NFPA 72.	Within 6 months



F-22	Fire Protection	The required standpipe system is not provided for the building in accordance with the ACCORD standard.	Install a new standpipe system in accordance with ACCORD standard 5.4 and NFPA 14.	Within 6 months
			<p>A class III system shall be installed in buildings with the highest occupiable floor 10 m (33 ft.) above grade or more.</p> <p>A class I system shall be permitted in buildings protected throughout by an approved automatic sprinkler system.</p>	
F-23	Egress Lighting	Manual on-off switch is provided for emergency lighting units on each floor and each stair.	Remove manual on/off switches from emergency lighting units to prevent them from being switched off.	Within 1 month



F-24	Egress Lighting	Inspection, testing and maintenance for the emergency lighting system was not in accordance with The ACCORD standard.	Inspect, test and maintain the emergency lighting system in the accordance with The ACCORD standard. Keep written records on-site.	Within 3 months
------	-----------------	---	--	-----------------