## **FIRE SAFETY INSPECTION REPORT**

## **EPCOT APPARELS LTD**JOYDEBPUR ROAD, CHANDANA, JOYDEBPUR

**OTHER FACTORIES: EPCOT JEANS LTD** 





## SUMMARY

Epcot Apparels Ltd was surveyed for fire safety on 5/11/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.



**Table 1. Findings And Recommendations** 

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	The boiler room on the ground floor is not separated by fire-rated construction due to multiple unprotected windows.	Separate the boiler room by a minimum 2-hr fire-rated construction. Seal and/or protected all openings to maintain the required fire separations	Within 3 months





F-2 Fire Rated Construction

Areas used for combustible storage are not separated by fire-rated construction.

Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction.







F-3 Fire Rated Construction

The exit stairs are not separated from work areas and other spaces on each floor by firerated construction.

Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors.

If fire doors are required to be held open for functional reasons, provide automaticclosing devices tied to the fire alarm system.







F-4 Fire Rated Construction

Unsealed penetrations and openings are located in the fire-rated floor/ceiling assemblies.

Provide a minimum 2-hr firerated shaft to separate the utility risers from each floor level. Within 3 months

Seal all penetrations and openings in floor/ceiling assemblies to maintain the fire separation.







F-5 Egress

Egress doors and gates with locking features are provided at all exit stair openings and discharge.

Remove locking features from all egress doors and gates.

Immediate

If locks are required for security reasons, utilize special door locking features complying with NFPA 101.







F-6 Egress

Storage was located in the West exit stair discharge.

Remove all storage from exit stairs and egress paths.







F-7 **Egress** 

The aisles were not completely clear.

Provide clear aisle widths of 36-in.

Within 3 months





F-8

Fire Protection The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.

Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.

Design within 4 months, install within 9 months









F-9

Fire Protection Inspection, testing, and maintenance for the fire alarm system was not in accordance with NFPA 72.

Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.



F-10 Fire Protection

The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.

Remove single-station smoke alarms. Provide automatic smoke detection throughout the building in accordance with NFPA 72.

Within 6 months





F-11 Egress Lighting

Inspection, testing, and maintenance for the emergency lighting system were not in accordance with The ACCORD Standard.

Inspect, test and maintain the emergency lighting system in accordance with The ACCORD standard. Keep written records on-site.

