

Four Brothers Fashion - Unit 2 (Ref. 9235)

66-68 Haji Deen Mohammad Road, Dhaka Uddyan, Beribadh, Mohammadpur, Dhaka

(+23.763376N, 90.343331E)

15.MARCH.2014



Identified Priority 2 Concerns

Typical internal columns, while matching the details set out in the structural drawings, produce a 'yellow' result from the column load run-down.

While not an immediate concern, a factor of safety between 1.5 and 1.86 is sufficient to warrant a review of design loads and stresses.

COLUMN SCHEDULE								
COLUMN TYPE	NUMBER OF COLUMN	UP TO PLINTH LEVEL	GROUND FLOOR	1ST FLOOR	2ND FLOOR	3RD FLOOR	4TH FLOOR	5TH TO 8TH FL.
C3	Nos	12"x27" 14-22mm $\varnothing$	10"x25" 14-22mm $\varnothing$	10"x25" 14-22mm $\varnothing$	10"x25" 12-22mm $\varnothing$	10"x25" 12-22mm $\varnothing$	10"x25" 12-22mm $\varnothing$	10"x25" 6-16mm $\varnothing$ 6-22mm $\varnothing$
C4	Nos	12"x32" 16-22mm $\varnothing$	10"x30" 16-22mm $\varnothing$	10"x30" 16-22mm $\varnothing$	10"x30" 14-22mm $\varnothing$	10"x30" 14-22mm $\varnothing$	10"x30" 14-22mm $\varnothing$	10"x30" 4-16mm $\varnothing$ 10-22mm $\varnothing$
C5	Nos	16"x27" 16-25mm $\varnothing$	16"x27" 16-25mm $\varnothing$	16"x27" 14-25mm $\varnothing$	16"x27" 12-25mm $\varnothing$	16"x27" 10-25mm $\varnothing$	16"x27" 6-25mm $\varnothing$ 4-25mm $\varnothing$	16"x27" 6-20mm $\varnothing$ 4-22mm $\varnothing$
C6	Nos	12"x22" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm	10"x20" 10-20mm $\varnothing$ + 8-10mm
ALL TIE BARS ARE 10mm $\varnothing$ @ 8" C/C								
		DRAWING TITLE						
		REVISIONS						
		16						
		 MR. JALIL UDDIN Project Engineer Design Department						
		 MR. JALIL UDDIN Project Engineer Design Department						
		 MR. JALIL UDDIN Project Engineer Design Department						
		 MR. JALIL UDDIN Project Engineer Design Department						
		 MR. JALIL UDDIN Project Engineer Design Department						

Identified Priority 3 Concerns

Priority 3 Concern



Lack of waterproofing layer has led to small amount of ponding at roof level.

No signs of water ingress were visible from within, however the ponding witnessed (during the dry season) suggests that it is a potential problem for the future if left untreated.



Note also the small pile of bricks. This load is not immediately concerning, but should be removed and prevented in future.

Water Ingress at Roof Level



No signs of water ingress visible on the soffit above 8th floor level.

Note that, as mentioned in the Priority Actions list, the lack of waterproofing at roof level leaves the potential for water ingress to develop over the long-term future of the building.

Priority Actions

Problems Observed Summary

ITEM 1: (Priority 2) 'Yellow' result from column load run-down, requiring further investigation before final structural safety sign-off.

ITEM 2: (Priority 3) Lack of waterproofing at roof level, leading to the potential for water ingress to develop in future.

Item 1 and actions

‘Yellow’ result from column load run-down, suggesting possible overloading of columns and requiring some further investigation.

Priority 1 (Immediate – Now)

- None required.

Priority 2 (within 6 – weeks)

- Factory engineer to review design, loads and column stresses, particularly in areas more heavily loaded by boiler at 1st and 4th floors.
- Verify in-situ concrete stresses, either by cores or existing cylinder strength data, for 4 typical internal columns.

Priority 3 (within 6-months)

- Produce and actively manage a loading plan for all floor plates within the factory, giving consideration to floor capacity and column capacity.

Item 2 and actions

Lack of waterproofing layer at roof level. No current signs of water ingress, but ponding suggests the potential for future problems if left untreated.

Priority 1 (Immediate – Now)

- None required.

Priority 2 (within 6 – weeks)

- None required.

Priority 3 (within 6-months)

- Apply a waterproofing membrane to roof level, with appropriate perimeter drainage.
- Monitor soffit of 8th floor to ensure that signs of water ingress do not develop.