

FIRE SAFETY INSPECTION REPORT

Factory Name: Kaniz Fashions Limited

ACCORD ID: 23756

ADDRESS: Plot no. A80 (part), A81 & A82, BSCIC Industrial Area, Konabari, 1700, Gazipur

Other Factories: None



Inspected By: Md. Anayet Hossain & Mohammad Atick

Date: 26 Sep, 2019.

Fire Safety Inspection Report

Factory Name: Kaniz Fashions Limited

Introduction:

ACCORD ID: 23756

Kaniz Fashions Limited was surveyed for fire safety on 19 August, 2019 by The Accord Inspection Team. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections. Table 1 summarizes the major fire safety issues identified during the inspection.

Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.



Findings & Recommendations :

Factory Name: Kaniz Fashions Limited

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.



SI No.	Category	Findings	Required Action	Remediation Time Frame
1	Fire Rated Construction	The exit stair enclosures are separated from work areas and other spaces on each floor by fire-rated construction. Fire Doors have been provided with proper hour rating. But doors are kept open and installation of magnetic hold open device to interface with Fire Alarm System have been done but the devices are not interfaced with any approved FACP. Moreover Exit stair enclosures have unprotected openings within 10 feet towards production floor at two stairs.	The exit stair enclosure shall be provided with a minimum 1-hr fire resistance rating for buildings with 3 or fewer stories and a minimum of 2-hr. fire resistance rating for buildings 4 or more stories. Provide 0.75 hr. fire rated door and seal all penetrations and openings by 1 hr. fire rated fire rated barrier construction for building with 3 or fewer stories. Provide 1.5 hr. fire rated door and seal all penetrations and openings by 2 hr. fire rated fire rated barrier construction for building with 4 or more stories. Provide a fire-resistive rated assembly between the exterior exit stairs and the building up to 10 ft. beyond the end of the stair to achieve the required separation. The rated assembly shall be approved and/or designed by a qualified fire protection engineer. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic closing devices tied to the fire alarm system.	Within 3 months





2	Fire Rated Construction	The fire pump room is not provided with adequate fire separation.	Provide fire pump room with 2 hr rated fire separation when not sprinklered and 1 hr rated fire separation when provided with automatic sprinklers in accordance with NFPA 20 Or, Physically separate the pump room from the protected building by a minimum of 50 ft. (15.3 m) in accordance with NFPA 20	Within 3 months
---	-------------------------	---	--	-----------------






3	Fire Rated Construction	Rooms used for combustible storage are not separated by fire rated construction. Location: wastage go down shed at ground floor adjacent to the mail building	Separate the dedicated storage rooms by minimum 1-hr fire-rated construction. Provide 0.75 hr. fire rated door and seal all penetrations and openings by 1 hr. fire rated fire rated barrier construction.	Within 3 months
---	-------------------------	---	---	-----------------





4	Fire Rated Construction	Dining area is not separated from other occupancies with fire rated assemblies.	Re-locate the dining area or separate the dining area from other occupancies with 2-hr fire rated construction.	Within 3 months
---	-------------------------	---	---	-----------------



5	Boiler or furnace room	Boiler or furnace room is not properly separated by fire rated construction with other Occupancies/Areas (specify the occupancy/area, location and construction materials of room).	1. Boilers or other heat producing equipment shall be separated from other occupancies by a minimum 1-hr (2-hr for highrise building) fire rated construction (wall, floor, slab etc). Seal all penetrations and openings (door, window etc.) should be protected by 0.75-hr (45 min) fire rated materials to maintain the fire separation if required. All exhaust systems shall discharge to the exterior of the building in a safe location. Or Relocate it to exterior of the building and maintain a minimum 3m (10 ft.) spatial separation distance from the building.	Within 3 months
---	------------------------	---	---	-----------------



6	Storage in Exit Stair	Storage was located in the exit stair.	Remove all storage from exit stairs.	Immediately
---	-----------------------	--	--------------------------------------	-------------






7	Fire Protection System	The high-rise building has an occupied floor greater than 23 meter (75 feet) and is not provided with automatic sprinkler protection. The large occupant loads, heavy fuel loading, and anticipated extended egress times warrant sprinkler protection.	Provide an automatic sprinkler protection throughout the building in accordance with NFPA 13.	Design within 04 Months & Installation Within 09 Months
---	------------------------	---	---	---



8	Emergency Egress Lighting	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles.	3 months
9	Fire Detection and Alarm System	The existing fire alarm & detection system is not installed properly. Still few areas are out of detection system.	Submit the as-built design/drawing of fire alarm & detection system to Accord for review.	Within 06 Months (Design review & Modification of the system)



10	Exit Sign	Exit sign not provided at exit.	Lighted exit signs shall be placed at entrance to an exit. Additional exit signs shall be placed throughout the facility anywhere the continuation of the egress is not obvious. Lighted exit signs shall be provided with either battery backup or uninterruptable power supply systems and shall be continuously illuminated.	Within 1 month
11	Manual On/Off Switch	Manual on-off switch is provided for emergency lighting / exit signage units.	Remove manual on/off switches from emergency lighting / exit signage units to prevent them from being switched off.	Within 1 month



12	Fire Detection System (ITM)	Inspection, testing, and maintenance for the fire alarm system is not in accordance with NFPA 72 or as per Accord standard.	Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72 or as per Accord standard.	Within 3 month (After completion of the installation)
13	Inspection, testing, and maintenance	Inspection, testing and maintenance of the standpipe system is not in accordance with NFPA 14.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 14 and ACCORD standards.	Within 3 Months
14	Inspection, testing, and maintenance	Inspection, testing, and maintenance for the exit sign and emergency lighting system was not in accordance with The ACCORD standard.	Inspect, test and maintain the exit sign and emergency lighting system in the accordance with The ACCORD standard. Keep written records on-site.	Within 3 Months
15	Inspection, testing, and maintenance	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10.	Inspect, test and maintain the portable fire extinguishers and keep written records on- site, in accordance with NFPA 10 and ACCORD standards.	Within 3 Months



16	Stair designation	Building did not have stair designation signs and occupant load signs at required locations.	Provide stair designation signs and occupant load signs at required locations.	1 week
----	-------------------	--	--	--------

