

FIRE SAFETY INSPECTION REPORT

HANNAN KNIT & TEXTILES LTD.
505, KALMESHOR, BOARD BAZAR, DHAKA



ACCORD
on Fire and Building Safety in Bangladesh

May 19, 2014

SUMMARY

Hannan Knit & Textiles Ltd. was surveyed for fire safety on 5/19/2014 by Hughes Associates, Inc. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.

Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	Areas used for storage on the ground floor are not separated by fire-rated construction.	If a separate storage room is may not feasible, provide defined storage areas and limit the storage arrangement as follows: - Maximum height of 2.4m and maximum area of 23m ² - If sprinkler protected: maximum height of 3.66m and maximum area of 93m ² .	Within 3 months



F-2	Fire Rated Construction	The exit stairs are not separated from work areas, other spaces on each floor by fire-rated construction.	Provide minimum 1.5-hr fire rated doors and seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors.	Within 3 months
-----	-------------------------	---	--	-----------------



F-3	Fire Rated Construction	Unsealed penetrations and openings are located in exit stair enclosures. The east exit has the opening on all floors.	Seal all penetrations and openings in exit stair enclosure walls to maintain the fire separation.	Within 3 months
-----	-------------------------	---	---	-----------------



F-4	Egress	Egress doors / gates with locking features are provided at building exits, exit stairs, along egress routes, exit discharge. These locking features can be found on all exits, on all floors throughout the factory.	Remove locking features from all egress doors / gates. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Immediate
-----	--------	--	---	-----------



F-5	Egress	Exit capacity is not adequate for the occupant load. Floor 1 the occupant load is 505 and the exit capacity is 476. Floor 2 the occupant load is 550 and the exit capacity is 476.	Specify appropriate upgrade based on conditions: - Reduce occupant load to not more than available exit capacity 9476) occupants.	Immediate
-----	--------	--	--	-----------

F-6	Egress	Collapsible gates are provided at building exits, exit stairs, along egress routes, exit discharge. These were at exit access on all floors for all four exit stairwells as well as all three exit discharges	Replace all gates / sliding doors along the means of egress with side-hinged, swinging egress doors. If locks are required for security reasons, utilize special door locking features complying with NFPA 101.	Within 1 month
-----	--------	---	---	----------------



F-7	Fire Protection	The fire alarm system is antiquated, not a listed system, and does not provide alarm and notification features consistent with acceptable standards.	Replace the fire alarm system with a new, listed addressable fire alarm system in accordance with NFPA 72.	Design within 4 months, install within 9 months
-----	-----------------	--	--	---



F-8	Fire Protection	Inspection, testing, and maintenance for the fire alarm system not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.	Within 3 months
-----	-----------------	--	---	-----------------

F-9	Fire Protection	The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.	Remove single station smoke alarms. Provide automatic smoke detection throughout the building in accordance with NFPA 72.	Within 6 months
-----	-----------------	--	---	-----------------



F-10	Fire Protection	The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.	Replace the single-station smoke alarms with automatic smoke detectors tied into the fire alarm system. Configure the fire alarm system to initiate occupant notification upon activation of any two smoke detectors in addition to the manual fire alarm stations.	Within 6 months
------	-----------------	--	---	-----------------



F-11	Egress Lighting	Inspection, testing, and maintenance records for the emergency lighting system were not available.	Inspect, test and maintain the emergency lighting system in accordance with The ACCORD standard. Keep written records on-site.	Within 3 months
------	-----------------	--	--	-----------------