

Cottonex Fashions Limited

Plot No. 12 & 13, Kalurghat Heavy I/A, Mohora, Chandgaon, Chattogram-4208

(22.384306, 91.869389)

19 October 2023



Building Information

1. **Production Building:** Nine-storied (G+8) reinforced concrete (RC) building including a partial storey at the roof.
2. **Utility Building:** RC building of two storied (G+1) with fire pumphoom in the basement.
3. **Security Post:** Single-storied reinforced concrete (RC) building.

Observations

Inconsistencies in Design report




Table 3.1: Equivalent Crushing Strength of Concrete (Column)

Sample No.	Core test result	Diameter of Core (inch)	Diameter Effect	Damage Effect	Modified Core test result	Average	kc	Number of sample	Standard deviation	coefficient of variation	Equivalent Concrete strength according to ACI 562 sec. 6.4.3
1	5960	2.640	1.04	1.06	6575.36	6481.58	2.4	2	132.62	0.02	5445.03
2	5790	2.640	1.04	1.06	6387.81						

4-nos of concrete cores taken from column (5210psi, 3870psi, 5960psi & 5790psi); but two core value (5960psi & 5790psi) used in calculating the equivalent concrete strength.

Also, total 14 sets of cylinder test reports was available on site, but location was not mentioned in the reports.

• **Earthquake/Seismic Load:**

The calculation of earthquake loads conforms to BNBC. These calculations are based on the Section 2.5; Part # 6 of BNBC.

For the calculation of possible earthquake load on the whole structure The Equivalent Static Force Method is adopted as Lateral Force Method [BNBC '06; Part # 6; Section # 2.5.5.1].

As per equivalent static force method total design base shear is calculated from the following equation.

$$V = \frac{ZIC}{R} W \quad [\text{Ref: BNBC-2006; Part\# 6; Chapter-2; Equation \# 2.5.1}]$$

Where,

Z = Seismic Zone Coefficient [BNBC '06; Part # 6; Table # 6.2.22]
= 0.15 (Gazipur is under Seismic Zone 2)

I = Structural Importance Coefficient [BNBC '06; Part # 6; Table # 6.2.23]
= 1.0 (Standard Occupancy Structures)

R = Response Modification Coefficient for Structural System
[BNBC '06; Part # 6; Table # 6.2.24]
= 9 (for Dual system share wall with IMRF RCC Portion)
[Fictorial evidence for verification is provided in 00.03. Appendix II_Detail Investigation Report]

W = Total Seismic Dead Load [BNBC '06; Part # 6; Section # 2.5.5.2]

C = Numerical coefficient given by the following relation

$$C = \frac{1.25S}{T^{2/3}} W$$

Response modification co-efficient, R value considered as 9 for IMRF (Dual system) but no calculation/justification is provided for the consideration.

7.6 Design Review of Foundation

According to soil test report done by "Soil Investigation" dated March 2017, capacity of 600mm dia piles with length of 39m is given below;

Bore Hole No.	Allowable Total Pile Capacity (Tons) FoS=3.0	Average Allowable Total Pile Capacity (Tons) FoS=3.0	Average Allowable Total Pile Capacity (Kips) FoS=2.5
B.H. -1	113.45	113.6409091	272.7381818
B.H. -2	110.75		
B.H. -3	121.5		

B.H. -4	114.8	Average Allowable Total Pile Capacity (Tons) FoS=3.0	Average Allowable Total Pile Capacity (Kips) FoS=2.5
B.H. -5	81.5		
B.H. -6	106.25		
B.H. -7	113.85		
B.H. -8	109		
B.H. -9	119.9		
B.H. -10	127.95		
B.H. -11	131.1		

Pile capacity calculation in design report

As per provided design report in pile capacity calculation factory used the average with data of eleven (11) boreholes. But some bore hole capacity is lower than the average value. Building engineer is required to provide calculation/justification for using the average value in pile capacity calculation.

Live load consideration

Observation: Production Building

INDUSTRIAL, STORAGE & HAZARDOUS (Occupancy - G, H & J)	Workshop, factory, warehouse			3.0	2.7
		1 Light workroom without storage		3.0	2.7
		2 Machinery hall & circulation area		4.0	4.5
		3 Factory, workshop etc.		5.0	4.5
		4 Manufacturing : light		6.0	4.5
		heavy		12.0	9.0 ⁽⁵⁾
		ice		15.0	9.0 ⁽⁵⁾
		5 Printing plant :			
		Press room		7.0	11.0
		Composing and linotype room		5.0	9.0 ⁽⁵⁾
		Paper storage room		12.0	9.0 ⁽⁵⁾
		6 Motor room, fan room etc. including the weight of machinery		7.5	4.5
		7 Cold storage, grain storage		15.0	9.0 ⁽⁵⁾
		8 Storage warehouses : light		6.0	4.5
		heavy		12.0	9.0
		9 Foundries		20.0	12.0

Minimum storage live load 6 kPa in BNBC

Live load considered 5 kPa on the storage areas which doesn't comply BNBC requirement.



Live load consider 5 kPa on the storage areas



Storage on floor

Dampness at ceiling of roof floor

Observation: Production Building



Dampness on the ceiling of the roof floor was observed. Building engineer is required to seal the source of water and repair the damp areas with suitable methods.

Column susceptible to vehicle impact

Observation: Production Building



Column at loading-unloading zone

Column adjacent to the loading-unloading area is susceptible to vehicle impact. The building engineer is required to provide separate barrier and signage to avoid possible vehicle impact on column.

Signage of water ponding on roof



Water ponding on the roof



Signage of water ponding on the roof

The factory is required to improve roof drainage system with adequate slope and provide sufficient water outlets to drain out water.

Observation: Production Building

Falling Hazard



Falling hazard from stair roof top



Falling hazard from stair roof top

Falling hazard observed in the stair roof top. Building engineer is required to take necessary measures to avoid possible falling hazard.

Inconsistencies in Design report

7.6 Design Review of Foundation

According to soil test report done by "Soil Investigation" dated March 2017, capacity of 600mm dia piles with length of 39m is given below:

Bore Hole No.	Allowable Total Pile Capacity (Tons) FoS=3.0	Average Allowable Total Pile Capacity (Tons) FoS=3.0	Average Allowable Total Pile Capacity (Kips) FoS=2.5
B.H. -1	113.45		
B.H. -2	110.75	113.6409091	272.7381818
B.H. -3	121.5		

B.H. -4	114.8		
B.H. -5	81.5		
B.H. -6	106.25		
B.H. -7	113.85		
B.H. -8	109		
B.H. -9	119.9		
B.H. -10	127.95		
B.H. -11	131.1		

As per provided design report in pile capacity calculation factory used the average data of eleven (11) boreholes. But some bore hole capacity is lower than the average value. Building engineer is required to provide calculation/justification for using the average value in pile capacity calculation.

Pile capacity calculation in design report

Mismatches in as built drawings



Marked beams layout not matched with on-site condition

Cantilever beams shown in drawing of utility building at stair roof top, but not found on site.
 Building engineer is required to confirm the location of the beams and update the drawings.

Problems Observed

Production Building:

Item 1: Inconsistencies in Design report.

Item 2: Live load consideration.

Item 3: Dampness at ceiling of roof floor.

Item 4: Column susceptible to vehicle impact.

Item 5: Signage of water ponding on roof.

Item 6: Falling Hazard.

Utility Building:

Item 7: Inconsistencies in Design report.

Item 8: Mismatches in as built drawings.

Priority Actions

Item No.	Observation	Recommended Action Plan	Recommended Timeline
01	Inconsistencies in Design report. (Production Building)	Building engineer is required to address the inconsistencies in the design report.	6-weeks
02	Inconsistencies in Design report. (Production Building)	Carryout remedial works where required.	6-months
03	Live load consideration. (Production Building)	Building engineer is required to prepare live load plan as per BNBC requirements.	6-weeks
04	Live load consideration. (Production Building)	Implement and maintain the floor live load as per the prepared load plan.	6-weeks
05	Dampness at ceiling of roof floor. (Production Building)	Building engineer is required to seal the source of water and repair the damp areas with a suitable method.	6-weeks
06	Column susceptible to vehicle impact. (Production Building)	The building engineer is required to provide separate barriers and signage to avoid possible vehicle impact on the column.	6-months

Item No.	Observation	Recommended Action Plan	Recommended Timeline
07	Signage of water ponding on roof. (Production Building)	Building engineer is required to improve the roof drainage system with adequate slope and provide sufficient water outlets to drain out water.	6-months
08	Falling Hazard. (Production Building)	Building engineer is required to take necessary measures to avoid possible falling hazard.	6-weeks
09	Inconsistencies in Design report. (Utility Building)	Building engineer is required to address the inconsistencies in the design report.	6-weeks
10	Inconsistencies in Design report. (Utility Building)	Carryout remedial works where required.	6-months
11	Mismatches in as built drawings. (Utility Building)	Building engineer is required to confirm the location of the beams and update the drawings.	6-weeks