

FIRE SAFETY INSPECTION REPORT

M.I.M. FASHION WEAR LTD.

ACCORD ID: 12288

**226/1, TILARGATI, SHINGBARI ROAD, TONGI,
GAZIPUR, BANGLADESH.**

OTHER FACTORIES: NONE



ACCORD
on Fire and Building Safety in Bangladesh

October 18, 2015

SUMMARY

M.I.M. Fashion Wear Ltd. was surveyed for fire safety on 10/18/2015 by Jensen Hughes. This summary identifies the major deficiencies that were identified during the inspection.

The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.

Table 1. Findings And Recommendations

No.	Category	Finding	Recommendation	Remediation Timeframe
F-1	Fire Rated Construction	Unsealed electrical shafts are located in the fire-rated floor of 1st floor.	Provide a minimum 2-hr fire-rated shaft to separate the utility risers from each floor level and seal all penetrations in floor/ceiling assemblies to maintain the fire separation.	Within 3 months
 				
F-2	Fire Rated Construction	Rooms used for combustible storage on ground floor are not separated by a minimum 1-hr fire-rated construction.	Provide dedicated storage rooms separated by minimum 1-hr fire-rated construction.	Within 3 months



F-3	Fire Rated Construction	Areas used for combustible storage on ground floor open to the factory are not properly defined and/or not within limits.	Provide defined storage areas and limit the storage arrangement as follows: - Maximum height of 2.45m (8 ft) and maximum area of 23m ² (250 ft ²) Separate areas of unenclosed combustible storage by a minimum clear distance of 3m (10 ft).	Within 3 months
-----	-------------------------	---	--	-----------------




F-4	Fire Rated Construction	The boiler room is not separated by fire-rated construction due to non-rated door.	Separate the boiler room by a minimum 1-hr fire-rated construction for non-high rise. Seal and/or protect all openings to maintain the required fire separations. Provide proper ventilation and consult a qualified engineer.	Within 3 months
-----	-------------------------	--	--	-----------------

When located to the exterior of a building, separate the boiler by a minimum distance of 3m (10 ft).




F-5	Fire Rated Construction	All exit stairs are not separated from work areas and other spaces on each floor by fire-rated construction due to unprotected openings and penetrations. This finding is based on current construction plans. If building plans change and do not exceed 3 floors total fire ratings in the recommendation can be changed to 1-hr.	Separate the exit stairs from from work areas and other building spaces on all floor levels by minimum 2-hr fire-rated construction. Provide minimum 1.5-hr fire rated doors and seal all unprotected openings and penetrations to maintain the fire separation. Ensure that all fire doors are self-closing and positive latching, and are provided with fire exit (panic) hardware where serving production floors or assembly occupancies. If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system. Once fire doors are installed, every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets ACCORD standard 6.8.3.1.	Within 3 months
-----	-------------------------	---	--	-----------------





F-6	Egress	Handrails are not provided on both sides of the all exit stairs.	Provide handrails on both sides of the exit stair. New handrails shall have a minimum height of 865 mm (34 in.) and a maximum height of 965 mm (38 in.) as measured from the leading edge of the tread. Intermediate handrails shall be provided when the stair width exceeds 2.2 m (87 in.) .	Within 3 months
-----	--------	--	--	-----------------



F-7	Fire Protection	The fire alarm system is antiquated, not a listed system and does not provide alarm and notification features consistent with acceptable standards.	Replace the fire alarm system with a new, listed automatic fire alarm system in accordance with NFPA 72 and ACCORD standards.	Design within 4 months, install within 9 months
-----	-----------------	---	---	---



F-8	Fire Protection	Inspection, testing and maintenance for the fire alarm system is not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system and keep written records on-site, in accordance with NFPA 72 and ACCORD standards.	Within 3 months
-----	-----------------	--	---	-----------------

F-9	Fire Protection	Fire department connection is not provided.	Provide fire department connection in accordance with ACCORD standard 5.5.4.	Within 3 months
-----	-----------------	---	--	-----------------

F-10	Fire Protection	Inspection, testing and maintenance of the standpipe system is not in accordance with NFPA 14.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 14 and ACCORD standards.	Within 3 months
------	-----------------	--	--	-----------------

F-11	Fire Protection	Fire pump is not provided and appears to be needed for the standpipe system fire demand.	Provide a fire pump in accordance with NFPA 20 and ACCORD standards, or provide an alternative water supply source capable of meeting the required fire protection demand, subject to ACCORD approval.	Within 6 months
F-12	Fire Protection	Standpipe system is required for the building, which has an occupiable floor 10 m (33 ft) or more above grade. This is required upon completion of construction.	Install a new class III standpipe system in accordance with ACCORD standard 5.4 and NFPA 14. A class I system shall be permitted in buildings protected throughout by an approved automatic sprinkler system.	Within 6 months



F-13	Fire Protection	The building is equipped with single-station smoke alarms. Smoke alarm activation sounds only a local alarm and does not provide automatic fire alarm notification of occupants.	Remove single-station smoke alarms. Provide automatic smoke detection throughout the building, tied into the fire alarm system, in accordance with NFPA 72 and ACCORD standards.	Within 9 months
------	-----------------	--	--	-----------------



F-14	Egress Lighting	Inspection, testing and maintenance for the emergency lighting system was not in accordance with ACCORD standards.	Inspect, test and maintain the emergency lighting system in the accordance with ACCORD standards. Keep written records on-site.	Within 3 months
F-15	Egress Lighting	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes of office area.	Test the emergency lighting system on each floor and provide additional emergency fixtures to supply adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and along exit discharge paths and a minimum 2.5 lux along exit access aisles.	Within 3 months