

INITIAL FIRE SAFETY INSPECTION REPORT

JM Fabrics Ltd. (Extension 2)

RSC ID: 26564

Geographical Coordinates: 24.090815847774174, 90.3696377479108

Address: South Nayapara, 6 No Dogri, Bhawal, Mirzapur

Other Factories: JM Fabrics Ltd. [RSC ID: 9497]; JM Fabrics Ltd. (Extension) [RSC ID: 24603]



**Inspected By: Md. Anisuzzaman, Mahfuza Khanom, Md. Najmul Huda &
Md. Kawsar Rubaiat**

Date: 05-March-2026

Fire Safety Inspection Report

JM Fabrics Ltd. (Extension 2)

Introduction:

JM Fabrics Ltd. (Extension 2) complex was surveyed for fire safety on **05-Mar-2026** by The RSC Inspection Team. The purpose of the survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the RSC. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Limitations

The information in this fire safety inspection report was obtained during a visit to the facility and during interviews with local factory management. It has not been possible to provide independent verification for all the information and data collected, and, therefore, The RSC cannot accept general responsibility for omissions or errors arising from inaccuracies in this report from the information obtained.

The findings and recommendations in this report are not intended to imply, guarantee, ensure or warrant compliance with any government regulations. Additionally, the results do not imply in any way that compliance with the findings or recommendations as stated in this report will eliminate all hazards, risks or exposures or that hazards, risks or exposures not referred to in this report do not exist. Compliance with the findings and recommendations stated in this report does not relieve the factory owner from obligation to comply with specific project requirements, industry standards, or the provisions of any local government regulations.

General Factory Information

Structures covered under this RSC ID-26564 are as follows, with

Two Under Construction Structures: a. Gate No. 2 & ATM Booth (140 Sq. ft); b. Sewage Treatment Plant (STP).

SL No	Building Name	Building Construction Period	Approval Date & Authority	Occupied	Structure type	Construction Category
1	Building-4 (Industrial Building): G+6 Storied Total Floor Area: 2,12,640 Sq. ft	Apr-2023 to Aug-2025	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Sep-2025	RCC	New
2	Building-5 (Storage Building): G+6 Storied Total Floor Area: 2,06,925 Sq. ft	Sep-2022 to Jul-2024	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Aug-2024	RCC	New
3	Building-6 (RMG Building): G+4 Storied Total Floor Area: 5,37,333 Sq. ft	Aug-2024 to Oct-2025	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Partially Occupied since Jan-2026	RCC	New
4	Building-7 (Utility Building 1): G+2 Storied Total Floor Area: 20,035 Sq. ft	Jun-2025 to Mar-2026	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Partially Occupied since Mar-2026	RCC	New

5	Building-8 (Utility Building 2): G+1 Storied Total Floor Area: 6,725 Sq. ft	Jun-2025 to Mar-2026	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Partially Occupied since Mar-2026	RCC	New
6	Gate No. 1 & Fire Control Room: Single Storied Total Floor Area: 936 Sq. ft	Nov-2025 to Mar-2026	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Mar-2026	RCC	New
7	Underground Water Tank & Pump Room: Single Storied Total Floor Area: 6,219 Sq. ft	Mar-2025 to Nov-2025	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Nov-2026	RCC	New
8	LPG Station: Single Storied Total Floor Area: 668 Sq. ft	Apr-2025 to June-2025	No Approval	Jun-2025	Steel	New
9	Compressor Shed: Single Storied Total Floor Area: 4,400 Sq. ft	Jan-2025 to Apr-2025	Approved on 19-Mar-2025 from LGED, Gazipur (DC Committee)	Apr-2025	Steel	New

Factory Address: South Nayapara, 6 No Dogri, Bhawal, Mirzapur.

Findings & Recommendations :

Table-1,2 & 3 summarize the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue. An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design/installation constraints, shall be submitted to the RSC for review.

Table-1: Building-4 (Industrial Building): G+6, RCC.

SI No.	Category	Findings	Required Action	Remediation Time Frame
F-01	Means of Egress	The exit stair enclosures are not separated from work areas and other spaces on each floor by fire-rated construction. Location(s): All floors, Building-4. Non-Compliance reason (s): 1. Unprotected opening from lift machine room on the both stairs. 2. Non-functional fire doors. 3. Lack of certificate & technical datasheet installed fire doors on site.	The exit stair enclosure shall be provided with a minimum of 2- hr. fire resistance rating for buildings 4 or more stories. Provide 1.5 hr. fire rated door and seal all penetrations and openings by 2 hr. fire rated fire rated barrier construction for building with 4 or more stories in accordance with section 6.3.1.2 of RSC Technical Guidelines (Standard)¹ V1.0. Provide a fire-resistive rated assembly between the exterior exit stairs and the building up to 10 ft. beyond the end of the stair to achieve the required separation. The rated assembly shall be approved and/or designed by a qualified fire protection engineer. Ensure that the fire doors are self-closing and positive latching, and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic closing devices tied to the fire alarm system. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification. The clearance under the bottom of a door shall be a maximum of 3/4 in. (19 mm).	Within 3 Months



F-02	Means of Egress	Aisles were found missing in several locations throughout the building. Location(s): 2nd,3rd, 4th & 5th floor of the Building-4.	Provide minimum aisle widths of 36-in. Aisles mark shall be clearly visible.	Within 1 Month
				

F-03	Means of Egress	Fire evacuation maps are not posted at the entrance of all exit stairs and do not match the on-site conditions. Location(s): Building-4.	Update the fire evacuation map and shall be posted at the entrance to each exit stair in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 13.3.	Within 3 Months
				
F-04	Means of Egress	Building does not have occupant load signs at required locations on all floors. Location(s): Building-4.	Post the occupant load for every assembly and production floor in a facility in a conspicuous space near the main exit or exit access doorway for the space in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.4.4	Within 1 Month

F-05	Means of Egress	Production floor does not discharge directly into exit enclosure, rather discharges into elevator shaft Location(s): 1st,2nd,3rd,5th & 6th floors of the Building-4.	As per RSC Technical Guidelines (Standard)-6.14.3: Openings into an exit enclosure other than unprotected exterior walls shall be limited to those necessary for exit access to the enclosure. In new and interim construction, an exit stairway shall not be built around a lift shaft unless both of them are located in a smoke-proof enclosure and made of a material with a fire-resistance rating required for the type of construction of the smoke-proof enclosure. Or, Provide a separate fire-rated exit from the production floor to the exit stair enclosure.	Within 3 Months
				

F-06	Means of Egress	Egress door serving 50 or more occupants but does not swing in the direction of egress travel. Location: 3rd & 4th floors of the Building-4.	Modify swing direction of egress doors to the direction of egress travel. Doors serving an occupant load of more than 50 shall swing in the direction (out-ward) of egress travel in accordance with section 6.8.1 of RSC Technical Guidelines (Standard)¹ V1.0.	Within 1 Month
				

F-07	Means of Egress	Directional signs are not provided where direction of the path of travel to an exit has changed. Location(s): All floors (Building-4).	Illuminated directional signs shall be provided where there is a change in the direction for the path of travel and the direction to an exit is not obvious in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.11.3.	Within 1 Month
				

F-08	Means of Egress	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes. Location(s): All floors (Building-4).	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths, and minimum 2.5 lux along exit access aisles. Illumination on means of egress shall meet in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 10.12.2.	Within 3 Months
				
F-09	Means of Egress	Building does not have stair/floor level designation signs at required locations on all floors. Location(s): All floors (Building-4).	Provide stair designation sign at each floor entrance from the stair to the floor in English and Bengali. Signs shall indicate the name of the stair and the floor level. Signs shall be posted adjacent to the door in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.9.3.	Within 1 Month

F-10	Means of Egress	The existing egress path is designed to discharge through a loading/unloading/ hazardous area, creating an unsafe exit route for occupants from the low/moderate hazard occupancy area. Location: Ground floor of the Building-4.	The egress route shall be reconfigured to eliminate discharge through the hazardous store area. A compliant exit path shall be established that avoids exposure to hazardous conditions while maintaining the minimum required number of exits, travel distance limits, and all other life safety provisions in accordance with RSC Technical Guidelines (Standard)¹ V1.0. Or , Provide a 2-hr exit access corridor through a loading/unloading/hazardous area leading to nearest exit.	Within 3 Months
 Shot with my Galaxy A13 05 March 2026  Shot with my Galaxy A13 05 March 2026				

F-11	Means of Egress	Doors swing out over aisles. Location: 6th floor (Building-4).	A landing shall be provided on both sides of doors used in the means of egress to facilitate uninterrupted egress of occupants. Door shall not swing out over stairs/aisles.	Within 3 Months
				


F-12	Means of Egress	Handrails are not provided on both sides of each exit stair on all floors. Having handrails on one side of said staircase may pose a falling hazard during evacuation. Location(s): Ground floor stairs & Ramps of the Building-4.	Provide handrails on both sides of the exit stair. New handrails shall have a minimum height of 865 mm (34 in.) and a maximum height of 965 mm (38 in.) as measured from the leading edge of the tread. Intermediate handrails shall be provided when the stair width exceeds 2.2 m (87 in.). Open guards shall have intermediate rails or pattern such that a sphere 200 mm (8 in.) in diameter cannot pass through any opening up to a height of 865 mm (34 in.). Handrail shall construct in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.12. .	Within 3 Months
		 Shot with my Galaxy A13 05 March 2026	 Shot with my Galaxy A13 05 March 2026	 Shot with my Galaxy A13 05 March 2026

F-13	Means of Egress	Uneven path of travel was observed in the exit discharge path due to construction purposes. Location(s): West side of Building-4.	Remove unnecessary items and level the exit path to the public way. Means of egress shall be maintained continuously free and clear of all obstructions.	Within 3 Months
				

F-14	Means of Egress	Exit signage are low illuminated during inspection Location(s): GF of the Building-4.	Regularly inspect all exit signage/directional signage as per RSC Technical Guidelines (Standard) ¹ V1.0. and replace/install lights as needed to illuminate signs.	Within 1 Month
				

F-15	Means of Egress	Exit stairs serve more than 5 stories and do not have the required re-entry provisions on all floors. Location(s): Building-4.	Every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets RSC Technical Guidelines (Standard) ¹ V1.0. Section 6.8.3.1.	Within 3 Months
F-16	Means of Egress	Parapets are found less than 42 inch. (Available: 36 inch) Location: Building-4.	Provide parapets or guards with a minimum height of 1067mm (42 inch.) in accordance with RSC Technical Guidelines (Standard) ¹ V1.0 Section 6.12.	Within 3 Months
				

F-17	Means of Egress	Uneven walking surface were found and exceed a slope of 1 in 20 in the direction of travel. Location: Ramp of the loading/unloading area at GF of the Building-4.	Walking surfaces shall be mostly level; however, shall not exceed a slope of 1 in 20 in the direction of travel unless meeting the requirements for ramps in 6.10 shall meet the requirements for RSC Technical Guidelines (Standard)¹ V1.0 Section 6.3.4.2	Within 3 Months
-------------	-----------------	--	---	-----------------



F-18	Fire Rated Construction	Elevator shafts open directly into the exit enclosure, which doesn't comply with RSC Technical Guidelines (Standard) , section 6.14.3. Location: Building-4. Non-Compliance: 1. Non-functional of the installed fire doors 2. Lack of Certificate & technical datasheet of the installed fire doors for verification.	Provide a minimum 2-hr fire rated elevator shaft to separate it from stair enclosure. No discharge is accepted through elevator shaft. Seal all openings to maintain fire separations. Collect certificate & technical datasheet of the installed fire doors & keep on site for verification.	Within 3 Months
 Shot with my Galaxy A13 05 March 2026		 Shot with my Galaxy A13 05 March 2026		 Shot with my Galaxy A13 05 March 2026

F-19	Fire Rated Construction	Areas used for in-process storage of combustible materials are open to the surrounding occupancy. Location(s): First floor of the Building-4.	Provide defined storage areas and limit the storage arrangement as follows: Maximum height of 2.45 m and maximum area of 23 m², and is separated by a minimum of 3.0 m (10ft) from other storage areas, and they do not exceed 10 percent of the building area of the story in which they occur. or, If sprinkler protected, Maximum height 12 ft (3.66 m) and maximum area of 1000 ft² (93 m²) and separated by at least 25 ft (7.62 m), and does not constitute more than 10 percent of the building area or 4000 ft² (372 m²) of the sprinklered area, whichever is greater. or, Enclose the storage area from the surrounding occupancy with a minimum 1-hour construction.	Within 3 Months
				

F-20	Fire Rated Construction	Bus bar penetrations through floor/ceiling assemblies are found unsealed due to the installed fire door non-functionality and unsealed penetrations. Location(s): All floors (Building-4). Non-Compliance: 1. Non-functional installed fire doors. 2. Lack of Certificate & technical datasheet of the installed fire doors for verification.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr. fire resistance rating. Installation shall be as per manufacturer's published installation guidelines and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification.	Within 3 Months
				

F-21	Fire Rated Construction	Plastic pipe penetrations through floor/ceiling assemblies are found unsealed. Location(s): Building-4. Non-Compliance: 1. Non-functional fire doors. 2. Lack of Certificate & technical datasheet of the installed fire doors & fire rated collar for verification.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr. fire resistance rating. Installation shall be as per the manufacturer's published installation guidelines and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required. Keep proper datasheet & certifications for installed fire rated collar and fire doors & accessories on-site for verification.	Within 3 Months
 Shot with my Galaxy A13 05 March 2026		 Shot with my Galaxy A13 05 March 2026		

F-22	Fire Alarm & Detection System (FADS)	The factory has installed a fire alarm and detection system that requires a detailed review to confirm compliance with NFPA 72 and RSC Technical Guidelines (Standard). Location(s): Building-4, Compressor shed & LPG station.	Submit the fire alarm and detection system design to RSC for review. Once the design is reviewed, install and modify the fire detection and alarm system throughout the building in accordance with review comment, RSC Technical Guidelines (Standard) and NFPA 72. After installation the owner shall conduct internal testing and commissioning and then contact the RSC for witness of final acceptance testing.	Design within 2 Months and modification/ installation with 4 Months
				
F-23	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance for the fire alarm system are not in accordance with NFPA 72. Location(s): Building-4, Compressor shed & LPG station.	Inspect, test, and maintain the fire alarm system and keep written records on-site, in accordance with NFPA 72 and RSC Technical Guidelines (Standard) ¹ V1.0.	Within 1 Month (after installation)

F-24	Fire Suppression System (SUPS)	Fire pump installation requires a detailed review to confirm compliance with NFPA 20 and RSC Technical Guidelines (Standard)¹ V1.0. Location(s): Building-4. [Note: Fire pump Capacity 1250GPM & 176 PSI(Brand-SFFECO). Location: Fire pump room under RSC ID-9497. Also serves other structures of ID: 9497.]	Submit as-built drawings, testing records, equipment certification and other relevant documentation to the RSC for review and approval. Submit the standpipe system drawing to RSC for review. Once reviewed, install or modify the standpipe system throughout the building in accordance with RSC Technical Guidelines (Standard)¹ V1.0. and NFPA 14 and 20. The factory management shall contact RSC to conduct the final acceptance testing after the installation, testing & commissioning.	Design within 2 Months and modification/ installation with 4 Months
		 Shot with my Galaxy A13 05 March 2026	 Shot with my Galaxy A13 05 March 2026	 Shot with my Galaxy A13 05 March 2026

F-25	Fire Suppression System (SUPS)	The highest occupied floor of the main building is over 75 feet above grade, mandating a sprinkler system along with a class I standpipe. The factory has installed a sprinkler system with a class III standpipe, requiring a detailed review to ensure compliance with NFPA 13, 14, 20, 22, and 24 and RSC Technical Guidelines (Standard). Location: Building-4.	Submit the fire Suppression System (fire pump, standpipe and sprinkler) design to RSC for review. Once the design is reviewed, install and modify the fire Suppression System throughout the building in accordance with review comment, RSC Technical Guidelines (Standard) and NFPA 13, 14, 20, 22 and 24. After installation the owner shall conduct internal testing and commissioning and then contact the RSC for witness of final acceptance	Design within 2 Months and modification/ installation with 4 Months
				

F-26	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the standpipe system are not in accordance with NFPA 25. Location: Building-4.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard) ¹ V1.0.s.	Within 1 Month (after installation)
F-27	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the sprinkler system are not in accordance with NFPA 25. Location: Building-4.	Inspect, test and maintain the sprinkler system and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard) ¹ V1.0.s.	Within 1 Month (after installation)
F-28	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the fire pump are not in accordance with NFPA 25. Location: Building-4 fire pump located at (Pump House Building (ID: 9497)).	Inspect, test and maintain the fire pump and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard) ¹ V1.0.s.	Within 1 Month (after installation)



F-29	Inspection, Testing & Maintenance (Fire)	Inspection, testing, and maintenance of portable fire extinguishers is not in accordance with NFPA 10. Location(s): Building-4.	Inspect, test and maintain the portable fire extinguishers and keep written records on- site, in accordance with NFPA 10 and RSC Technical Guidelines (Standard)¹ V1.0.	Within 1 Month
F-30	Inspection, Testing & Maintenance (Fire)	Inspection, testing, and maintenance for the exit sign and emergency lighting system was not in accordance with the RSC Technical Guidelines (Standard)¹ V1.0. Location(s): Building-4.	Inspect, test and maintain the exit sign and emergency lighting system in the accordance with the RSC Technical Guidelines (Standard)¹ V1.0. Keep written records on-site.	Within 1 Month

F-31	Fire Suppression System (SUPS)	Portable fire extinguishers are not installed throughout all facilities. Location(s): All floor except ground floors of the Building-4.	Install fire extinguishers at locations and heights in accordance with section 5.6 of RSC Technical Guideline (Standard)	Within 1 Month
 Shot with my Galaxy A13 05 March 2026				

F-32	Inspection, Testing & Maintenance (Fire)	The required no smoking signs are not present in the factory.	Smoking is prohibited in any garment factory building or separate storage building. Signs shall be posted in Bengali and English at all building entrances. If the factory creates a designated smoking area outside the building, information of these areas will be posted on the signs. Smoking sign shall post in accordance with section 13.5 of RSC Technical Guideline (Standard)	Within 1 Month
F-33	Inspection, Testing & Maintenance (Fire)	Written housekeeping policy was not found, which is required as per RSC Technical Guideline (Standard) section 13.6.	Establish written corporate and plant policies on housekeeping to ensure scheduled cleaning for floor, wall, ceiling, supply and return air ventilation systems. Promptly reschedule skipped cleanings. Provide a documented line of authority for authorizing a cleaning delay and rescheduling. As a general rule the maximum tolerable deposit thickness for loose fluffy lint is 13 mm (½ in.) over a maximum of 46.5 m2 (500 ft2). Limit dense deposits to 6 mm (¼ in.) and oil saturated deposits to 3.2 mm (⅛ in.).	Within 1 Month

Table-2: Building-5 (Storage Building): G+6 Storied, RCC.

SI No.	Category	Findings	Required Action	Remediation Time Frame
F-34	Means of Egress	The exit stair enclosures are not separated from work areas and other spaces on each floor by fire-rated construction. Location(s): Building-5. Non-Compliance: 1. Unprotected opening from lift machine room on the Stair-1. 2. Non-functional fire doors. 3. Inadequate certification & technical datasheet of installed fire doors and accessories. 4. Gap below fire door found more than 19 mm.	The exit stair enclosure shall be provided with a minimum of 2- hr. fire resistance rating for buildings 4 or more stories. Provide 1.5 hr. fire rated door and seal all penetrations and openings by 2 hr. fire rated fire rated barrier construction for building with 4 or more stories in accordance with section 6.3.1.2 of RSC Technical Guidelines (Standard)¹ V1.0. Provide a fire-resistive rated assembly between the exterior exit stairs and the building up to 10 ft. beyond the end of the stair to achieve the required separation. The rated assembly shall be approved and/or designed by a qualified fire protection engineer. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic closing devices tied to the fire alarm system. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification. The clearance under the bottom of a door shall be a maximum of 3/4 in. (19 mm).	Within 3 Months

 March 05, 2026 12:05 PM  March 05, 2026 1:07 PM  March 05, 2026 12:52 PM				
F-35	Means of Egress	Aisles were found missing in several locations throughout the building. Location(s): Several locations and floors, Building-5.	Provide minimum aisle widths of 36-in. Aisles mark shall be clearly visible.	Within 1 Month
 March 05, 2026 12:27 PM  March 05, 2026 1:41 PM				

F-36	Means of Egress	Fire evacuation maps are not updated as per site condition. Location(s): Building-5.	Update the fire evacuation map and shall be posted at the entrance to each exit stair in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 13.3.	Within 1 Month
F-37	Means of Egress	Changes in level were found more than 30 in. where RSC Technical Guidelines (Standard)¹ V1.0 Section 6.9 or 6.10 don't meet. Location(s): Building-5.	Changes in level exceeding 535 mm (21 in.) in elevation shall meet the requirements for stairs in 6.9 or ramps in 6.10. The change in level shall be readily apparent and if not, marked with additional signage or floor markings.	Within 3 Months
				

F-38	Means of Egress	Falling hazards are present at the loading-unloading area, which are situated at a high altitude. Location(s): Ground floor, Building-5.	Guards shall be provided at all open sides of means of egress that exceed 760 mm (30 in.) above the floor or finished ground below. New and interim: Guards shall have a minimum height of 1067 mm (42 in.). Open guards shall have intermediate rails or pattern such that a sphere 200 mm (8 in.) in diameter cannot pass through any opening up to a height of 865 mm (34 in.). Guard/Handrail shall construct in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.12.	Within 3 Months
				

F-39	Means of Egress	Directional signs are not provided where direction of the path of travel to an exit has changed. Location(s): All floors, Building-5.	Illuminated directional signs shall be provided where there is a change in the direction for the path of travel and the direction to an exit is not obvious in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.11.3.	Within 1 Month
				

F-40	Means of Egress	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes. Location(s): All floors, Building-5.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles. Illumination on means of egress shall meet in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 10.12.2.	Within 3 Months
				

F-41	Means of Egress	Doors in a means of egress were found less than 1 m (39 in.). Location(s): Ground floor, Inspection area, Building-5.	Doors in a means of egress shall have a minimum width of 1 m (39 in.) as per RSC Technical Guideline (Standard) section 6.5.6.	Within 3 Months
				

F-42	Means of Egress	Uneven path of travel was observed in the exit discharge path. Location(s): North side discharge path, Building-5.	Remove unnecessary items and level exit path to the public way. Means of egress shall be maintained continuously free and clear of all obstructions	Within 3 Months
				
F-43	Means of Egress	Exit stairs serve more than 5 stories and do not have the required re-entry provisions on all floors. Location(s): Building-5.	Every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets RSC Technical Guidelines (Standard)¹ V1.0. Section 6.8.3.1.	Within 3 Months

F-44	Means of Egress	Handrails are not provided on both sides of each exit stairs on all floors. Having handrails on one side of said staircase, may pose as a falling hazard during evacuation. Location(s): Ground floor, Building-5.	Provide handrails on both sides of the exit stair. New handrails shall have a minimum height of 865 mm (34 in.) and a maximum height of 965 mm (38 in.) as measured from the leading edge of the tread. Intermediate handrails shall be provided when the stair width exceeds 2.2 m (87 in.). Open guards shall have intermediate rails or pattern such that a sphere 200 mm (8 in.) in diameter cannot pass through any opening up to a height of 865 mm (34 in.). Handrail shall construct in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.12.	Within 3 Months
 March 05, 2026 2:19 PM  March 05, 2026 1:54 PM				

F-45	Fire Rated Construction	Unprotected openings in the exterior wall in two consecutive floors lying within 1.5 m and vertical spread of fire is not restricted. Location(s): W-N and W-S side, All floors (Building-5).	Provide flame barriers as similar as sunshades or cornices or projected wall at least 750 mm from the external face of the exterior wall. BNBC 2020 Part III chapter 3 clause 3.1.9.2.	Within 6 Months
				

F-46	Fire rated construction	Rooms used for storage of combustible materials are not separated from the surrounding occupancy/areas. From Office and Working area in floors, one of the exits discharges through storage rooms. Location(s): All floor of Building-5. Soda & Dyes Material Store (Ground floor, Building -5).	Rooms used for storage of combustible materials shall be separated from the surrounding occupancy with a minimum 1 hour construction in accordance with section 3.4.2.1.5 of RSC Technical Guideline (Standard).	Within 3 Months
 				

F-47	Fire rated construction	Penetrations through floor/ceiling assemblies are found unsealed. Location: Conveyor belt connecting with floors (from 4th to 1st floor), Building-5.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr. fire resistance rating. Installation shall be as per manufacturer published installation guideline and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required.	Within 3 Months
 March 05, 2026 2:27 PM  March 05, 2026 1:13 PM  March 05, 2026 1:50 PM				

F-48	Fire rated construction	Areas used for in-process storage of combustible materials are open to the surrounding occupancy. Location: 2nd and 1st floor (Building-5).	Provide defined storage areas and limit the storage arrangement as follows: Maximum height of 2.45 m and maximum area of 23 m² and is separated by a minimum 3.0 m (10ft) from other storage areas and they do not exceed 10 percent of the building area of the story in which they occur. or, If sprinkler protected, Maximum height 12 ft (3.66 m) and maximum area of 1000 ft² (93 m²) and separated by at least 25 ft (7.62 m) and does not constitute more than 10 percent of the building area or 4000 ft² (372 m²) of the sprinklered area, whichever is greater. or, Enclose the storage area from the surrounding occupancy with a minimum 1 hour construction.	Within 3 Months
				

F-49	Fire rated construction	The required fire separation distance for Building-5 does not comply with the requirements of BNBC 2020. Location(s): East side, Building-5.	The exterior walls shall have a fire resistance and opening protection as specified in BNBC 2020 Part 3 Table 3.2.2 & 3.2.3 and BNBC 2020 Part 3 Section 2.4.1.3.	Within 6 Months
				

F-50	Fire rated construction	It was observed that Elevator shafts open directly into the exit enclosure, which doesn't comply with RSC Technical Guidelines (Standard), section 6.14.3. The factory has claimed the lift landing doors are fire rated; however 3rd party listing certificate, listing labelling are missing during inspection. Location(s): Building-5.	Provide a minimum 2-hr fire rated elevator shaft to separate it from stair enclosure. No discharge is accepted through elevator shaft. Seal all openings to maintain fire separations. If the lift landing doors are fire rated, Keep proper datasheet & certifications for lift landing door on-site for verification.	Within 3 Months
				

F-51	Fire Rated Construction	Penetrations through wall assemblies are found unsealed. Location(s): Cable riser on all floors (Building-5). Non-compliance reason: 1. Unseal Penetrations. 2. Inadequate certification & technical datasheet of installed fire doors and accessories.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr. fire resistance rating. Installation shall be as per manufacturer published installation guideline and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification.	Within 3 Months
 March 05, 2026 1:25 PM		 March 05, 2026 1:30 PM		 March 05, 2026 1:39 PM

F-52	Fire Rated Construction	Penetrations through the floor/ceiling assemblies were observed to be sealed with Firestop Wrap strip. However, the required documents were not available at the time of inspection. Additionally, adequate pipe identification markings were not present on-site, preventing verification of the installed pipe type. Location(s): Plastic pipes, All floors, Building-5.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr fire resistance rating. Installation shall be as per manufacturer published installation guideline and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required.	Within 3 Months
				


F-53	Fire Alarm & Detection System (FADS)	The factory is installing a fire alarm and detection system that requires a detailed review to confirm compliance with NFPA 72 and RSC Technical Guidelines (Standard). Location(s): Building-5.	Submit the fire alarm and detection system design to RSC for review. Once the design is reviewed, install and modify the fire detection and alarm system throughout the building in accordance with review comment, RSC Technical Guidelines (Standard) and NFPA 72. After installation the owner shall conduct internal testing and commissioning and then contact the RSC for witness of final acceptance testing.	Design within 2 Months and modification/ installation with 4 Months
 March 05, 2026 1:38 PM  March 05, 2026 1:08 PM  March 05, 2026 1:32 PM				

F-54	Fire Suppression System (SUPS)	The highest occupied floor of the main building is over 75 feet above grade, mandating a sprinkler system along with a class I standpipe. Sprinkler installation is on going in lieu of addressable smoke and/or heat detectors. The factory has installed a sprinkler system with a class I standpipe, requiring a detailed review to ensure compliance with NFPA 13, 14, 20, 22, and 24 and RSC Technical Guidelines (Standard). Location(s): Building-5.	Submit the fire Suppression System (standpipe and sprinkler) design to RSC for review. Once the design is reviewed, install and modify the fire Suppression System throughout the building in accordance with review comments, RSC Technical Guidelines (Standard), and NFPA 13, 14, 20, 22 and 24. After installation, the owner shall conduct internal testing and commissioning, and then contact the RSC for witness of final acceptance testing.	Design within 2 Months and modification/ installation with 4 Months
 				
F-55	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the sprinkler system are not in accordance with NFPA 25. Location(s): Building-5.	Inspect, test, and maintain the sprinkler system and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard)¹ V1.0.s.	Within 1 Month (after installation)

F-56	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10. Location(s): Building-5.	Inspect, test and maintain the portable fire extinguishers and keep written records on- site, in accordance with NFPA 10 and RSC Technical Guidelines (Standard)¹ V1.0.	Within 1 Month
F-57	Inspection, Testing & Maintenance (Fire)	Inspection, testing, and maintenance for the exit sign and emergency lighting system was not in accordance with the RSC Technical Guidelines (Standard)¹ V1.0. Location(s): Building-5.	Inspect, test and maintain the exit sign and emergency lighting system in the accordance with the RSC Technical Guidelines (Standard)¹ V1.0.. Keep written records on-site.	Within 1 Month

Table-3: Building-6, 7, 8 & Others.

SI No.	Category	Findings	Required Action	Remediation Time Frame
F-58	Means of Egress	The exit stair enclosures are not separated from work areas and other spaces on each floor by fire-rated construction Location(s): Building-6. Non-compliance: Fire doors are not properly functional & penetrations.	The exit stair enclosure shall be provided with a minimum of 2-hr. fire resistance rating for buildings 4 or more stories. Provide 1.5 hr. fire rated door and seal all penetrations and openings by 2 hr. fire rated fire rated barrier construction for building with 4 or more stories in accordance with section 6.3.1.2 of RSC Technical Guidelines (Standard)¹ V1.0. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic closing devices tied to the fire alarm system. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification. The clearance under the bottom of a door shall be a maximum of 3/4 in. (19 mm).	Within 3 Months

				
F-59	Means of Egress	Aisles were found missing in several locations throughout the building. Location(s): All floors, Building-6.	Provide minimum aisle widths of 36-in. Aisles mark shall be clearly visible.	Within 1 Month
				

F-60	Means of Egress	Fire evacuation maps are not posted at the entrance of all exit stair. Location(s): All floors of Building-6, 7 & 8.	Fire evacuation maps shall be posted at the entrance to each exit stair in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 13.3.	Within 1 Month
F-61	Means of Egress	Changes in level were found 30 in. where RSC Technical Guidelines (Standard)¹ V1.0 Section 6.9 or 6.10 don't meet. Location(s): Building-6, 7 & 8.	Changes in level exceeding 535 mm (21 in.) in elevation shall meet the requirements for stairs in 6.9 or ramps in 6.10. The change in level shall be readily apparent and if not, marked with additional signage or floor markings.	Within 3 Months
				

F-62	Means of Egress	Exit passageway is not separated from the building interior due to non-rated openings. Location(s): Ground floor, Building-6.	Exit passageways shall have walls, ceilings, and floors that meet the same rating requirement as the exit that is being served and shall not be less than 1 hr fire-resistance rated construction as per RSC Technical Guidelines (Standard) 6.15.3.	Within 3 Months
 				

F-63	Means of Egress	Directional signs are not provided where direction of the path of travel to an exit has changed. Location(s): All floors, Building-6, 7 & 8.	Illuminated directional signs shall be provided where there is a change in the direction for the path of travel and the direction to an exit is not obvious in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.11.3.	Within 1 Month
 				

F-64	Means of Egress	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes. Location(s): All floors, Building-6, 7 & 8.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles. Illumination on means of egress shall meet in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 10.12.2.	Within 3 Months
				

F-65	Means of Egress	Exit sign not provided at exit. Location(s): All floors, Building-6, 7 & 8.	Lighted exit signs shall be placed at entrance to an exit. Additional directional exit signs shall be placed throughout the facility anywhere the continuation of the egress is not obvious. Lighted exit signs shall be provided with either battery backup or uninterruptable power supply systems and shall be continuously illuminated at all times. Exit Sign shall provide in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.11.	Within 1 Month
 				

F-66	Means of Egress	Some lighted exit signs were two-sided, so that they indicated an exit where there were none. Location(s): Ground & 1st floor, Building-6.	Ensure that lighted exit signs are only visible from the side that directs people toward an exit path.	Within 1 Month
				

F-67	Means of Egress	Doors in a means of egress were found less than 1 m (39 in.). Location(s): Ground floor, Prayer Room, Building-6. Available: 32 inches.	Doors in a means of egress shall have a minimum width of 1 m (39 in.) as per RSC Technical Guideline (Standard) section 6.5.6.	Within 3 Months
				

F-68	Means of Egress	A single means of exit has been provided on new construction. Location(s): Building-8.	The number of means of egress from any floor, story, or portion thereof shall not be less than 2 except where a single exit is permitted by RSC Technical Guideline (Standard), section 6.6.2. Provide additional exit and ensure that the exit doors or means of egress openings are located a distance apart as per RSC Technical Guideline (Standard) section 6.6.6.	Within 3 Months
				

F-69	Means of Egress	Uneven path of travel was observed in the exit discharge path due to construction purposes. Location(s): Building-6, 7 & 8.	Remove unnecessary items and level exit path to the public way. Means of egress shall be maintained continuously free and clear of all obstructions.	Within 3 Months
 				
F-70	Means of Egress	Building does not have occupant load signs at the required locations on all floors. Location(s): Building-6, 7 & 8.	Post the occupant load for every assembly and production floor in a facility in a conspicuous space near the main exit or exit access doorway for the space, in accordance with RSC Technical Guidelines (Standard)¹, V1.0, Section 6.4.4.	Within 1 Month

F-71	Means of Egress	Handrails are not provided on both sides of each exit stairs on all floors. Having handrails on one side of said staircase, may pose as a falling hazard during evacuation. Location(s): Building-7 & 8.	Provide handrails on both sides of the exit stair. New handrails shall have a minimum height of 865 mm (34 in.) and a maximum height of 965 mm (38 in.) as measured from the leading edge of the tread. Intermediate handrails shall be provided when the stair width exceeds 2.2 m (87 in.). Open guards shall have intermediate rails or pattern such that a sphere 200 mm (8 in.) in diameter cannot pass through any opening up to a height of 865 mm (34 in.). Handrail shall construct in accordance with RSC Technical Guidelines (Standard)¹ V1.0 Section 6.12.	Within 3 Months
				

F-72	Fire Rated Construction	Liquefied or compressed gas cylinders were located within the factory premises without adequate fire separation. Location: LPG Station.	Remove the liquefied or compressed flammable gas cylinders. The storage or use of liquefied or compressed flammable gas (LPG/CNG) cylinders within the factory building as per section 3.4.2.1.11 of RSC Technical Guidelines (Standard)¹ V1.0. Or, Factory shall follow the requirements RSC Published "SUPPLEMENTARY PAPER ON TECHNICAL GUIDANCE NOTE FOR USE OF LIQUIFIED OR COMPRESSED FLAMMABLE GAS IN FACTORY PREMISES" to use or store liquefied or compressed flammable gas cylinders in the factory premises.	Within 3 Months
		 March 05, 2026 2:19 PM	 March 05, 2026 2:19 PM	

F-73	Fire Suppression System (SUPS)	Portable fire extinguishers are not installed throughout all facilities. Location(s): Building-6, 7 & 8.	Install fire extinguishers at locations and heights in accordance with section 5.6 of RSC Technical Guideline (Standard)	Within 1 Month
				

F-74	Fire rated construction	It was observed that Elevator shafts open directly into the production floor without proper fire separation due to unprotected opening. The factory has claimed the lift landing doors are fire rated; however, 3rd party listing certificate was missing during inspection. Location(s): Building-6.	Elevator shaft shall be separated from the production area by 2 hours of fire-rated construction. 2-hr fire barriers shall be protected with a minimum 1.5-hr fire protective opening assemblies. If the lift landing doors are fire-rated, Keep proper datasheet & certifications for the lift landing door on-site for verification.	Within 3 Months
 March 05, 2026 12:45 PM		 Shot with my Galaxy A17 20 October 2025		 March 05, 2026 1:06 PM

F-75	Fire rated construction	Elevator shafts open directly into the exit passageway on the ground floor, which doesn't comply with RSC Technical Guidelines (Standard), section 6.14.3. The factory has claimed the lift landing doors are fire-rated; however, 3rd party listing certificate was missing during inspection. Location: Ground floor, Building-6.	Provide a minimum 2-hr fire rated elevator shaft to separate it from stair enclosure. No discharge is accepted through elevator shaft. Seal all openings to maintain fire separations. If the lift landing doors are fire-rated, Keep proper datasheet & certifications for the lift landing door on-site for verification.	Within 3 Months
		 05 Mar 2026 1:31 pm	 05 Mar 2026 1:32 pm	

F-76	Fire rated construction	Areas used for in-process storage of combustible materials are open to the surrounding occupancy. Location: 1st floor (Building-6).	Provide defined storage areas and limit the storage arrangement as follows: Maximum height of 2.45 m and maximum area of 23 m² and is separated by a minimum 3.0 m (10ft) from other storage areas and they do not exceed 10 percent of the building area of the story in which they occur. or, If sprinkler protected, Maximum height 12 ft (3.66 m) and maximum area of 1000 ft² (93 m²) and separated by at least 25 ft (7.62 m) and does not constitute more than 10 percent of the building area or 4000 ft² (372 m²) of the sprinklered area, whichever is greater. or, Enclose the storage area from the surrounding occupancy with a minimum 1 hour construction.	Within 3 Months
				

F-77	Fire Rated Construction	Penetrations through floor/ceiling assemblies are found unsealed. Location(s): BBT & cable tray on all floors (Building-1). Non-compliance reason(s): 1. Unsealed Penetrations. 2. Installed Fire door is not properly functional. 3. Gap below fire door more than 19 mm.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr./ 2-hr. fire resistance rating. Installation shall be as per manufacturer published installation guideline and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required. Keep proper datasheet & certifications for installed fire doors & accessories on-site for verification.	Within 3 Months
 05 Mar 2026 12:37 pm  March 05, 2026 12:37 PM  05 Mar 2026 12:37 pm				

F-78	Fire Rated Construction	Penetrations through the floor/ceiling assemblies were observed to be sealed with Firestop Wrap strip. However, the required documents were not available at the time of inspection. Adequate pipe identification markings were not present on-site, preventing verification of the installed pipe type. Location(s): Building-6.	Seal all penetrations and openings in floor/ceiling assemblies by a listed through-penetration fire stop system tested in accordance with ASTM E814 or approved alternative standard to maintain minimum 3-hr. fire resistance rating. Installation shall be as per manufacturer's published installation guideline and the certification authority guideline to ensure the fire-rating in accordance with section 4.7 of RSC Technical Guideline (Standard) Or, Provide a minimum 2-hr fire rated shaft to separate the penetration from each floor if required. Keep appropriate documentation & sample on-site for verification.	Within 3 Months
				

F-79	Fire Alarm & Detection System (FADS)	The factory has installed a fire alarm and detection system that requires a detailed review to confirm compliance with NFPA 72 and RSC Technical Guidelines (Standard). Location(s): Building-6, 7, 8 & other ancillary structures under this ID.	Submit the fire alarm and detection system design to RSC for review. Once the design is reviewed, install and modify the fire detection and alarm system throughout the building in accordance with review comment, RSC Technical Guidelines (Standard) and NFPA 72. After installation the owner shall conduct internal testing and commissioning and then contact the RSC for witness of final acceptance testing.	Design within 2 Months and modification/ installation with 4 Months
 March 05, 2026 1:38 PM  March 05, 2026 1:03 PM  March 05, 2026 1:03 PM				
F-80	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance for the fire alarm system is not in accordance with NFPA 72. Location(s): Building- 5, 6, 7, 8 & other ancillary structures under this ID.	Inspect, test and maintain the fire alarm system and keep written records on-site, in accordance with NFPA 72 and RSC Technical Guidelines (Standard)¹ V1.0.s.	Within 1 Month (after installation)

F-81	Fire Suppression System (SUPS)	The factory has installed a standpipe & Hose system that requires a detailed review to confirm compliance with NFPA 14,20, 24 and RSC Technical Guidelines (Standard). Location(s): Building- 6 & 7.	Submit the standpipe system drawing to RSC for review. Once reviewed, install or modify the standpipe system throughout the building in accordance with RSC Technical Guidelines (Standard)¹ V1.0. and NFPA 14, 20,22 and 24. After installation the owner shall contact the RSC for witness of conducting the final acceptance testing of the standpipe system.	Design within 2 Months and modification/ installation with 4 Months
 05 Mar 2026 2:10 pm  05 Mar 2026 2:26 pm  March 05, 2026 12:57 PM				

F-82	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the standpipe system are not in accordance with NFPA 25. Location(s): Building- 5, 6 & 7.	Inspect, test, and maintain the standpipe system and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard)¹ V1.0.s.	Within 1 Month (after installation)
F-83	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of the fire pump are not in accordance with NFPA 25. Location: Single storied-Underground Water Tank & Pump Room.	Inspect, test and maintain the fire pump and keep written records on-site, in accordance with NFPA 25 and RSC Technical Guidelines (Standard)¹ V1.0.s.	Within 1 Month (after installation)
F-84	Inspection, Testing & Maintenance (Fire)	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10. Location(s): Building-6, 7, 8 & other ancillary structures under this ID.	Inspect, test and maintain the portable fire extinguishers and keep written records on- site, in accordance with NFPA 10 and RSC Technical Guidelines (Standard)¹ V1.0.s.	Within 1 Month
F-85	Inspection, Testing & Maintenance (Fire)	Inspection, testing, and maintenance for the exit sign and emergency lighting system was not in accordance with the RSC Technical Guidelines (Standard)¹ V1.0. Location(s): Building-6, 7, 8 & other ancillary structures under this ID.	Inspect, test and maintain the exit sign and emergency lighting system in the accordance with the RSC Technical Guidelines (Standard)¹ V1.0.. Keep written records on-site.	Within 1 Month

F-86	Inspection, Testing & Maintenance (Fire)	The Building approval from appropriate authority are not available on-site for Building-LPG Station.	Get all the required licenses and permits from the proper issuing authority and keep it at site.	Within 1 Month
F-87	Inspection, Testing & Maintenance (Fire)	The required no smoking signs are not present in the factory.	Smoking is prohibited in any garment factory building or separate storage building. Signs shall be posted in Bengali and English at all building entrances. If the factory creates a designated smoking area outside the building, information of these areas will be posted on the signs. Smoking sign shall post in accordance with section 13.5 of RSC Technical Guideline (Standard).	Within 1 Month