

Logos Apparels Ltd. (10917)

No. 73, Ward No.06, Mouchak Kaliakoir, Gazipur Bangladesh


(+24.022065N, +90.297296E)

06.APRIL.2014



Identified Priority 2 Concerns


1st Priority 2 Concern




This area shows 5 longitudinal bars.

This column C2 at grid B6 was randomly checked with a Ferros scanning device.

This area shows 4 longitudinal bars.




The column C2 is supposed to have 5 bars each side.



Identified Priority 3 Concerns

1st Priority 3 Concern



Typical 127mm concrete slab (5in)

- The slab appears to be thinner than what is required. The span/depth ratio of slab = $6090/127 = 47 > 38$
- The design seems to lack a long term deflection analysis consideration.

Priority Actions

Problems Observed Summary

ITEM 1: (1st Priority 2) An inconsistency of column reinforcement between structural design and as-built structure

ITEM 2: (1st Priority 3) Depth of slab is very thin and the design seems to lack a consideration of long term deflection analysis.

Item 1 and actions

The Ferroskan image shows an inconsistency with the reinforcement configuration between the structural design and the as-built structure.

Priority 1 (Immediate – Now)

- None required

Priority 2 (within 6 – weeks)

- Building survey must be taken to verify the system with regard to reinforcement configuration
- Building engineer to verify the system to ensure the structural consistency between design and as-built structure

Priority 3 (within 6-months)

- Building engineer to check for non-compliance

Item 2 and actions

Very thin slabs could result in excessive long term deflections

Priority 1 (Immediate – Now)

- None required

Priority 2 (within 6 – weeks)

- Building Engineer to verify design and check with full compliance to design codes
- Long term deflection criteria to be justified

Priority 3 (within 6-months)

- If the slabs are found not to comply, then remedial details should be proposed and installed.