



Divine Intimates Ltd

Khowaznagar, Azimpara, Karnafuli, Chittagong

(22.314738 N, 91.841780 E)

10th January 2018






Observation



Paucity of details in As-Built drawings



Sub-beam at 5th floor




Sub-beam layout for 2nd floor



Details information were not found for section 13 (Lift core)

Sub-beam at 5th floor are not similar with typical floor. Sub-beam layout for 5th floor was not found in as built drawings. Also Sectional details of grid 13 was not available in provided drawings .



Cross section of Grid-A


Bracing pattern of marked two location was interchanged on site.



Over head RC water tank



Over head RC water tank



Roof Layout



Over head RC water tank

No structural details were available on provided drawings for over head water tanks



Problems Observed

Production Building

1: Paucity in as-built drawing.



Priority Actions



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Paucity of details in As-Built drawings	Building Engineer to survey as-built structure and prepare accurate as-built survey information with connection details for the building.	6-weeks
2	Paucity of details in As-Built drawings	Provide details information for over head water tanks.	6-weeks