



# Anowara Fashions Ltd.

35/A ,Hajigonj Road,Narayanganj.

(23.635106, 90.511905)

24<sup>th</sup> September 2018





# Observation




# Columns susceptible to vehicle impact

**Observations: Factory Building**



Impact protection not provided to columns at loading –unloading area. Columns are susceptible to impact loading from vehicles.



Ground Floor Layout



# No drawing for Generator Building



No drawings were available for generator building.



Generator Building



# Problems Observed

## Factory Building

1: Columns susceptible to vehicle impact.

## Generator Building

2: Lack of drawing for Generator Building.



# Priority Actions



| Item No. | Observation                                                  | Recommended Action Plan                                   | Recommended Timeline |
|----------|--------------------------------------------------------------|-----------------------------------------------------------|----------------------|
| 1        | Columns susceptible to vehicle impact. (Factory Building)    | Install a barrier to prevent vehicle impact in column.    | 6-weeks              |
| 2        | Lack of drawing for Generator Building. (Generator Building) | Prepare update as-built documentation Generator Building. | 6-weeks              |