

LZ Fashion Wear Ltd

Plot # 154, DEPZ (Ext.), Ganakbari, Savar, Dhaka
(23.943990,90.280182)



14th March 2015



Observations

Discrepancy between structural drawings and on-site observations


Observations




The holes appears to have been relocated into the adjacent slab. If holes did exist in the beams there would be significant questions regarding the strength of the slab and the stability system.

Discrepancies between architectural drawings and on-site observations

Observations



Steel roof structure replaced with concrete



South cantilever missing off elevations

Problems Observed

- Discrepancy between structural drawings and on-site observations
- Discrepancies between architectural drawings and on-site observations

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Discrepancy between structural drawings and on-site observations	Update structural drawings to reflect as-built condition	6-months
2	Discrepancies between architectural drawings and on-site observations	Update architectural drawings to reflect as-built condition	6-months