

Rahimaaziz Knitspin Ltd.

Enayetnagar, Bholail, Fatullah, Narayanganj

(23.619090N, 90.478626E)

11th March 2015



Observations

Missing element of diagonal wall bracing (north-east corner)



One bracing cable is missing in the wall in one bay

(Non-structural item)
**No fire protection observed on the steel
structure**



No fire protection observed on any of the steel structure

Priority Actions

Problems Observed

ITEM 1: Missing element of diagonal wall bracing (north-east corner)

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Missing element of diagonal wall bracing (north-east corner)	Replace missing bracing cable	6-weeks