



K.C Jacket Wear Company

Ratuti, Katchkura, Uttarkhan, Uttara, Dhaka

(23.857718, 90.465948)

30th June 2019





Observations



Apparently non-engineered fire escape stair of utility building.



Apparently non- engineering stair. Building engineer is required to check the adequacy of the stair.



Poor connection details



Poor connection details




Connection of the canopy


Observation : Building-1 (KC jacket building)



Canopy structure



Rafter connected with brick façade.



Connection between tension member and the brick façade wall.

Apparently inadequate connection of the canopy structure. Building engineer is required to check the connection for the uplift force.

Observation : Building-1 (KC jacket building)



Problems Observed

- 1: Apparently non-engineered fire scape at utility building.
- 2: Connection of the canopy.



Priority Actions



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Apparently non-engineered fire escape stair of utility building	Building engineer is required to check the adequacy of the fire escape stair.	6-weeks
2	Apparently non-engineered fire escape stair of utility building	Carry out any remedial works where necessary	6-months
3	Connection of the canopy	Building engineer is required to check the adequacy of the connection of canopy structure for the uplift force.	6-weeks
4	Connection of the canopy	Carry out any remedial works where necessary	6-months