



EVITEX DRESS SHIRT LTD.

Shirirchala, Bhabanipur, Joydevpur, Gazipur-1704, Bangladesh
(24.170253, 90.442684)

22 January & 25 February 2020





Observations



Electrical cables cut into and pass through main structural beams.



Electrical cable pass through beams.




Electrical Cables have been cut into and pass through main structural beams throughout various floor levels of the factory. Structural Engineer to Investigate and report on this matter to verify the Structural Integrity of the beams are not compromised.



Apparently inadequate concrete area in joints

Observation : Admin Building



The steel hip rafter is resting on base plate which is partially hanging. Building engineer is required to check the connection adequacy.

Observation : Admin Building



Problems Observed

- 1: Electrical cables cut into and pass through main structural beams.
- 2: Apparently inadequate concrete area in joint.



Priority Actions



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Electrical cables cut into and pass through main structural beams. (Factory Complex)	Building Engineer to Investigate and report on this matter to verify the Structural Integrity of the beams are not compromised.	6-weeks
2	Electrical cables cut into and pass through main structural beams. (Factory Complex)	Carry out any remedial works where necessary	6-months
3	Apparently inadequate concrete area in joint. (Admin Building)	Building engineer is required to check the connection adequacy of the base plate partially resting on RC column.	6-weeks
4	Apparently inadequate concrete area in joint. (Admin Building)	Carry out any remedial works where necessary	6-months