


Metro Knitting & Dyeing Mills Ltd. (9510)

Mouza-Basaid, S.A.-202, R.S.-909, Charabag, Ashulia, Dhaka

23.MARCH.2014



Identified Priority 1 Concerns

(None)

Identified Priority 2 Concerns

Reduce Storage Loading

Priority 2 Concern



Storage levels appeared slightly higher than allowable in localized areas distributed throughout the complex.



High Levels of Local Storage

Identified Priority 3 Concerns

(None)

Priority Actions

Problems Observed Summary

ITEM 1: (Priority 2) Generally slab loadings were acceptable. However, moderately high storage loadings were observed at localized areas throughout the complex.

Item 1 and Actions

Storage above allowable live loads within building A

Priority 1 (Immediate – Now)

- None

Priority 2 (within 6 weeks)

- Factory engineer to develop and actively monitor a loading plan for all floor plates within the factory giving consideration to slab, column and foundation capacity.

Priority 3 (within 6 months)

- None