

Revision : Issue 01
Date: 01.04.2014

GREEN

Northern Fashions Ltd. (9202)

Plot 16-18 Dakkin Panishail, EPZ Kaliakoir Road, Kashimpur, Gazipur, Dhaka
(+23.991154, +90.257172)

01.APRIL.2014

Client Summary Report

Observations & Actions

Written By Alex Nott – 01.04.14

Reviewed By Marc Tardif – 01.04.14

Approved By Geoff Minto – 08.04.14



ACCORD
on Fire and Building Safety in Bangladesh



Identified Priority 1 Concerns

(None)

Identified Priority 2 Concerns

(None)

Identified Priority 3 Concerns

(No Formal Loading Plan Available)

Priority 3 Concern



No formal loading plan was available at the time of inspection, very localized areas of higher than desirable storage were observed. However for the most part storage loads were very low.

Lack of Floor Loading Plan

Priority Actions

Problems Observed Summary

ITEM 1: (Priority 3) No floor loading plan was available at the time of inspection. Floors were for the most part reasonably loaded. However, localized areas of high storage were observed.

Item 1 and Actions

Lack of floor loading plan at the time of inspection

Priority 1 (Immediate – Now)

- None

Priority 2 (within 6 weeks)

- Develop a loading plan for all floor plates within the factory complex giving consideration to slab, beam and column capacity.

Priority 3 (within 6 months)

- Actively manage the existing loading plan for all floor plates within the factory complex.