

Genesis Fashions Ltd.

126/1 Kadda Nandun, Kadda Bazar, Gazipur Sadar, Gazipur
(23.985952, 90.356677)

24th October 2015



Observations

Loose bolts



Bolted connections are found
loosened

Observation


Discontinuity and Corrosion



Discontinuity and Corrosion found in the portal frame bracing at column F-17

Observation

High Parapet wall



High parapet wall over the roof may fall if it subjects to the horizontal (wind) force

Observation



High parapet wall over the roof may fall if it subjects to the horizontal (wind) force

Observation

Priority Actions

Problems Observed

ITEM 1: Loosened bolts needs to be tightened.

ITEM 2: Repair of the corrosion protection paint.

ITEM 3: Verify lateral stability of the parapet wall.

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Tighten loose bolts.	Check the connections and tighten loose bolts.	6-months
2	Repair corrosion protection paint.	Check structural elements paints and repair corrosion protection paint.	6-months
3	Verify lateral stability of the parapet wall.	Building Engineer should check parapet wall stability.	6-months