

# Universe Knitting Garments Ltd. (Unit- 1)

Jamgora Chourasta, Ashulia Road, Savar  
23.936590N, 90.290692E

4<sup>th</sup> November 2015




# Observations

# Lack of Vertical and Horizontal Bracing on Main Production Shed



**Lack of Vertical and Horizontal Bracing on Main Production Shed**

# Poor Roof Insulation and Corrosion on Roof



Poor Roof Insulation and Corrosion on Roof

# Non-Engineered Truss Connection in Warehouse



**Non-Engineered Connection of Roof Truss in Warehouse**



# Priority Actions

# Problems Observed

**ITEM 1:** Lack of lateral stability in production building.

**ITEM 2:** Non engineered roof connections in warehouse.

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Stability of the structure needs to be verified by the Building engineer	Building Engineer to verify lateral stability of the structure.	6-weeks
2	Stability of the structure needs to be verified by the Building engineer	Building Engineer to check, collect information and complete structural drawings and documentation as soon as possible.	6-months
3	Non engineered roof structure	Engineer to review the roofs and make recommendations as to how the roofs are to be brought up to standards	6-weeks
4	Non engineered roof structure	Carry out remedial actions as required	6-months