

BD DESIGNS PRIVATE LTD

Plot No: 48-49, sector: 03, Karnaphuli EPZ, Chittagong-4204, Bangladesh
(22.276610N, 91.794507E)


7th November 2015



Observations

Hairline Crack on a Beam at 5th Floor Ceiling

Observation



Hairline crack observed on a beam at 5th floor ceiling.

Canopy at the East Side of the Building

Observation



The design and connections of the canopy at the east side of the building lacks proper detailing.

Priority Actions

Problem Observed:

ITEM 1: Hairline Crack on a Beam at 5th Floor Ceiling

ITEM 2: Stability of the Canopy at East End of the Building

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Hairline Crack on a Beam at 5th Floor Ceiling	Building Engineer to get the crack properly repaired.	6-months
2	Hairline Crack on a Beam at 5th Floor Ceiling	Building Engineer to monitor the repaired beam to check if new cracks occur.	6-months
3	Stability of the Canopy at East Side of the Building	Stability and the connection details of the canopy at the East side of the building to be checked by the Building Engineer.	6-months
4	Stability of the Canopy at East Side of the Building	Make necessary alterations to the structural members of the canopy, if required.	6-months