

# RGR Sweater Ltd

Madhakhala Shreepur, Gazipur  
(24.180929N, 90.435039E)

7<sup>th</sup> November 2015



# Observations

## **Building – 2 (Steel shed)**



## Observation – Building 2

## **Building – 3 (dining)**



Discontinuous top reinforcement in the beam of ground floor



No vertical bracing observed

## Observation – Building 3

# Priority Actions

# Problems Observed

**ITEM 1:** : Stability of the Building 3 needs to be verified by the building engineer.

**ITEM 2:** : Lateral stability of the roof for Building 2 needs to be verified by the Building engineer.

| Item No. | Observation                                                  | Recommended Action Plan                                                                      | Recommended Timeline |
|----------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------------------|
| 1        | Discontinuous top reinforcement on beams on the ground floor | Building Engineer to carry out a stability analysis of the Building 3.                       | 6-weeks              |
| 2        | Missing horizontal braces on the roof for lateral stability  | Building Engineer to carry out a stability analysis and provide additional stability system. | 6-months             |