

# CONFIDENCE KNITWEAR LTD.

Dhanuya, Nayanpur, Sreepur, Gazipur  
(24.2547672N, 90.3885037E)

3<sup>rd</sup> November 2015



# Observations

## Problem Observed in the New Production Building:

- Uncontrolled construction material storage on the roof
- Overloaded storage areas

## Observations

# Uncontrolled construction material storage on the roof




Uncontrolled construction material storage

# Overloaded storage areas



## Observations – New Production Building



3<sup>rd</sup> Floor

# Priority Actions

# Problems Observed

**ITEM 1: Overloaded storage areas**

**ITEM 2: Cracks on the beams and partition walls**

| Item No. | Observation                                            | Recommended Action Plan                                                                              | Recommended Timeline |
|----------|--------------------------------------------------------|------------------------------------------------------------------------------------------------------|----------------------|
| 1        | Uncontrolled construction material storage on the roof | Remove construction materials from the roof                                                          | 6-weeks              |
| 2        | Overloaded storage areas                               | The quantity of the stored materials must be reduced to the level specified by the original designer | 6-weeks              |
| 3        | Overloaded storage areas                               | Building Engineer to provide a Load Plan for each level                                              | 6-weeks              |
| 4        | Overloaded storage areas                               | Reduce loading to the recommendations of the loading plans                                           | 6-months             |