



Remi Holdings Ltd.

Plot No. 244-245 & 250-251, Road-01, Adamjee Nagar, EPZ, P.S.
Shiddhirganj, Narayanganj
(23.681092N, 90.517714E)

22 June 2016






Observations



Missing Connection bolts in the Roof steel frame of the B1 (Main Production building)





Missing Connection bolts
in the Roof steel frame
connection observed of
the B1 (Main Production
building)



Missing Connection bolts in the Roof steel frame of the B1
(Production building)



Cracks in interior brick walls of Main production building.



Cracks in interior brick
walls observed in several
location

Cracks in interior brick walls



Corrosion in sheeting and structural members of production building.



Corrosion & Leakage in roof sheeting member



Corrosion in steel member

Corrosion in sheeting and structural members



Priority Actions



Problems Observed

Building 1 (Main Production building)

- ITEM 1:** Missing Connection bolts in the Roof steel frame of the Production building.
- ITEM 2:** Cracks in interior brick walls of production building.
- ITEM 3:** Corrosion in sheeting and structural members of production building



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Building 1. Missing Connection bolts in the Roof steel frame of the Main Production building	Building Engineer to identify all the omissions and supervise remedial works to the missing bolts in the connections.	6-months
2	Building 1: Cracks in interior brick walls of main production building.	Building engineer investigate extent of cracks.	6-months
3	Building 1. Corrosion in sheeting and structural members of main production building	Building Engineer to issue a schedule of remedial works for bracing reinstatement and corrosion protection.	6-weeks
4	Building 1. Corrosion in sheeting and structural members of main production building	Remedial works to be carried out.	6-months