

Crystal Industrial Bangladesh Private Ltd

Sa plot 2013, Master Para, Kewa, Sreepur, Gazipur, Dhaka
(24.18587N,90.429583E)
5th March 2014



Observations

Water Damage on water Tank

Water Damage on reinforced concrete structure due to leaking water.



Water damage

Embankment



The embankment on the eastern side of the building carries loads of a wall separating the estate. The embankment shows sign of slippage. Slope stability to be assessed.

Embankment

Priority Actions

Problems Observed

1. Water damage to Concrete Frame supporting Water tank
2. Embankment Stability to East of building

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Water damage to concrete supporting water tank	Fix leaks on water tank to prevent further damage to concrete.	6-months
2	Slope stability of embankment	Slope stability to be assessed to prevent slippery of embankment.	6-months