



RAM Apparel Ltd.

Block# A, Plot# 49/1, Ward# 20 P.O.# Salna Bazar 1703 Tak Kathora
(24.028530, 90.378460)

8th March 2020





Observations



Additional imposed load on the cantilever



Additional build-up constructed on the cantilever slab. Building engineer is required to check the slab adequacy for this additionally imposed dead loads.



Problems Observed

Utility Building:

01: Additional imposed load on the cantilever.



Priority Actions



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Additional imposed load on the cantilever	Building engineer is required to check the slab adequacy for this additionally imposed loads.	6-weeks
2	Additional imposed load on the cantilever	Carry out any remedial works where necessary.	6-months