

MILLENNIUM TEXTILES (SOUTHERN) LTD - New Building

Bara Rangamatia, Zirabo, Ashulia, Savar
(23.911121, 90.302724)
24 October 2022



Building information

- Building- 2: 6 storied (G+5) building
- Building-3: 2 storied (G+1) building
- Building-4: Single storied building

Observations

Column damage due to trolley impact



Column damage due to trolley impact in Building-2

Building engineer is required to repair the damage surface of the column and provide adequate protection system to resist trolley impact.

Problems Observed

Building-2:

Item 1: Column damage due to trolley impact.

Priority Actions

Item No.	Observation	Recommended Action Plan	Recommended Timeline
01	Column damage due to trolley impact (Building-2.	Building engineer is required to repair the damage surface of the column and provide adequate protection system to resist trolley impact	(6-weeks)