

Azim & Sons (Pvt.) Ltd. (10340)

Gacha Road, Fakir Market, Gazipur

(+23.898375N, 90.398232E)

15.APRIL.2014



ACCORD
on Fire and Building Safety in Bangladesh



Identified Priority 1 Concerns

(None)

Identified Priority 2 Concerns

(None)

Identified Priority 3 Concerns

Lateral Restraint System

Produce and actively manage a loading plan for all floors within the factory giving consideration to slab, beam and column capacity.



We require that these items be investigated in a Detailed Engineering Assessment

Flat slab in the main factory...this creates uncertainty regarding the lateral stability of the building.

Lateral Restraint System



Produce and actively manage a loading plan for all floors within the factory giving consideration to slab, beam and column capacities.

Priority Actions

Problems Observed Summary

ITEM 1: (Priority 3) Lateral Restraint System

ITEM 2: (Priority 3) Produce and actively manage a loading plan for all floors within the factory giving consideration to slab, beam and column capacities.

Item 1 and actions

Lateral Restraint System

Priority 1 (Immediate – Now)

- None

Priority 2 (within 6 weeks)

- Carry out a Detailed Engineering Assessment on the building structures, looking specifically at overall lateral stability.

Priority 3 (within 6 months)

- Implement any works deemed necessary by the Detailed Engineering Assessment.

Item 2 and actions

Loading Plan

Priority 1 (Immediate – Now)

- None

Priority 2 (within 6 weeks)

- None

Priority 3 (within 6 months)

- Produce and actively manage a loading plan for all floors within the factory giving consideration to slab, beam and column capacity.