



Progress Apparels (Bangladesh) Limited

M.S-S.F.B# 01 & 02, Adamjee EPZ, Siddhirganj
(23.677097, 90.525516)
9th April 2017






Observations



Structural column layout to be verified



Column layout plan-2nd floor



Additional Column

Marked column was not observed on site. The structural column layout to be updated by the factory engineer.

Observations



Problems Observed

1: Structural column layout to be verified



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Structural column layout to be verified	Building Engineer is required to investigate the structural column layout.	6-weeks
2	Structural column layout to be verified	Update the as-built drawings to the as-constructed status.	6-weeks