

# KC Lingerie (10908)

57/1, Water Works Road, Godnail, Narayanganj  
(+23.641693N, +90.519447E)

22.APRIL.2014



**ACCORD**  
on Fire and Building Safety in Bangladesh



## Identified Priority 3 Concerns

- No Loading Plans available.

Priority 3 Concern



It was indicated that all factory floors were designed for 100psf live load. Although no floors were observed to be loaded in excess of 100psf, no slab loading plan was provided nor were there any signs of slab load monitoring.

**No Loading Plan**

# Priority Actions

## Problems Observed Summary

**ITEM 1: (Priority 3) No loading plans was provided, nor did load monitoring measures appear to be in effect.**

## Item 1 and actions

No Loading Plan available.

### Priority 1 (Immediate – Now)

- None

### Priority 2 (within 6 weeks)

- The Factory Engineer is to develop loading plans which can be displayed at each floor level taking into account slab, beam and column capacities.

### Priority 3 (within 6 months)

- Implement and actively monitor the loading plans.