

# Vision Composite Knit Ltd (10330)

## Vision Garments Ltd

B-47, Purbo Rajashon Road, Savar, Bangladesh


(+23.84964N, 90.28593E)

26.May.2014



# Identified Priority 3 Concerns

# 1st Priority 3 Concern



The foundation plans shows a combined footing for the columns at Grid A5 and Grid A5a. However, the detail is missing from the drawings.

**Lack of structural information with regard to the combined footing**

# Priority Actions

## Problems Observed Summary

**ITEM 1: (1<sup>st</sup> Priority 3) Lack of information regarding the combined footing**

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	1st Priority 3 - Lack of information regarding the combined footing.	Building Engineer to advise as-built footing detail If necessary, carry out excavation to ascertain the actual layout of the footing.	6-months