



Arunima Apparels Ltd. (Building-2)

Plot I/10, Block -K, Section - 2, Mirpur, Dhaka- 1216

(23.810636, 90.358261)

4th March, 2018





Observations



Implement floor load management program



Implement the floor load management program as per the floor load carrying capacity and ensure that the workers understand the loading requirements.



Dampness throughout the building



Dampness on internal walls



Dampness on façade



Loose filler material through isolation gap





Priority Actions



Problems Observed

1. Implement floor load management program.
2. Dampness throughout the building.



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Implement floor load management program	Implement floor load management program as per floor capacity.	6-weeks
2	Dampness throughout the building	Investigate the reason of dampness and carry out remedial works with suitable method(where necessary).	6-months