

Vision Composite Knit Ltd (103330)

Vision Garments Ltd

B-47, Purbo Rajashon Road, Savar, Bangladesh


(+23.84964N, 90.28593E)

26.May.2014



Identified Priority 3 Concerns

1st Priority 3 Concern



The foundation plans shows a combined footing for the columns at Grid A5 and Grid A5a. However, the detail is missing from the drawings.

Lack of structural information with regard to the combined footing

Priority Actions

Problems Observed Summary

ITEM 1: (1st Priority 3) Lack of information regarding the combined footing

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	1st Priority 3 - Lack of information regarding the combined footing.	Building Engineer to advise as-built footing detail If necessary, carry out excavation to ascertain the actual layout of the footing.	6-months