

Sweatertech Ltd.

Plot # 898, 1351, Gacha Road, Gazipur Sadar, Gazipur.
(23.939125N, 90.370392E)
10 March 2015



Observations

Lightning pole at roof top

Observations



Lightning poles at the roof top appear to be attached in a temporary manner

Edge Protection

Observations



No edge protection observed for areas under construction

Observations

Priority Actions

Problems Observed

ITEM 1: Lightning poles at the roof top to be secured in a robust way or removed.

Non Structural Observation:

ITEM 2: Fall protection is missing at slabs and stairs under construction.

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Lightning poles at the roof top to be secured in a robust way or removed	Lightning pole at the roof top is to be secured in a robust way or removed.	6-weeks