

FIRE SAFETY INSPECTION REPORT

Four H Apparels Ltd. (New Building)

ACCORD ID: 23457

295, Jalalabad, Hathazari Road, Chittagong, Bangladesh.


(22.405423, 91.818243)

OTHER FACTORY (S): Four H Apparels Ltd. (Accord ID: 10377)



Inspected By: Md. Ferdaus Jaman

Date: 27th September, 2018

3	Egress	Building did not have occupant load signs at the required locations.	Provide occupant load signs at the required locations.	Within 1 month
				
4	Emergency Lighting ITM	Inspection, testing, and maintenance for the emergency lighting system were not in accordance with The ACCORD standard.	Inspect, test and maintain the emergency lighting system in the accordance with The ACCORD standard. Keep written records on-site.	Within 1 month

