

# **FIRE SAFETY INSPECTION REPORT**

**AKH ECO APPARELS LTD.**

**ACCORD ID: 12256**

**495- BALITHA, SHAH- BELISHWER, DHAMRAI,  
DHAKA.**

**OTHER FACTORIES: NONE**



**ACCORD**  
on Fire and Building Safety in Bangladesh

Bangladesh Accord  
Foundation

October 29, 2015

## **SUMMARY**

**AKH ECO APPARELS LTD. was surveyed for fire safety on 10/29/2015 by Jensen Hughes. This summary identifies the major deficiencies that were identified during the inspection.**

**The purpose of this survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.**

**Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.**

**An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the Accord for approval.**

**Table 1. Findings And Recommendations**

No.	Category	Finding	Recommendation	Remediation Timeframe
-----	----------	---------	----------------	-----------------------

F-1	Fire Protection	Orange tabs were found on some sprinkler heads throughout the building.	Remove all orange tabs from sprinkler heads.	Within 3 months
-----	-----------------	---	--	-----------------



F-2	Egress Lighting	Manual on-off switch is provided for emergency lighting units throughout the building.	Remove manual on/off switches from emergency lighting units to prevent them from being switched off.	Within 1 month
-----	-----------------	--	--	----------------

