

Best Shirts Ltd

35, Kunia, Borobari, PO. National University, Gazipur-1704
(23.936602N, 90.38689E)

30 March 2014



Building Observations

Truss supports at roof steel frame



Non engineered truss supports



Truss support missing

Lateral Stability of Steel roof to be verified

Priority Actions

Problems Observed

ITEM 1: Repair missing steel support and verify lateral stability as well as supports of steel roof

Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	Repair missing steel support and verify lateral stability as well as supports of steel roof	Missing steel support to be replaced	6-weeks
2	Repair missing steel support and verify lateral stability as well as supports of steel roof	Engineer to verify the lateral stability of the steel roof	6-months
3	Repair missing steel support and verify lateral stability as well as supports of steel roof	Engineer to verify the load transfer of the steel roof to the supports and propose repair	6-months