

# Pioneer Knitwears (BD) Ltd.

AT-Jamirdia, Habirbari, Valuka, Mymensingh  
(24.3193067N, 90.3770503E)

26 April 2014



# Observations

# **Wall Vertical bracing in the Single-Storey Steel-framed Warehouse missing/not tightened.**



Missing steel vertical cross-bracing in walls of Warehouse (Building 7).



Cross-bracing sagging slightly in some buildings.

# Priority Actions

# Problems Observed

**ITEM 1:** Missing/sagging bracing in small number of steel single-storey buildings

| Item No. | Observation                                                             | Recommended Action Plan                | Recommended Timeline |
|----------|-------------------------------------------------------------------------|----------------------------------------|----------------------|
| 1        | Missing/sagging cross-bracing in small number of steel-framed buildings | Provide vertical bracing to Building 7 | 6-months             |
| 2        | Missing/sagging cross-bracing in small number of steel-framed buildings | Tighten cross-bracing where necessary  | 6-months             |