



Sharaf Apparels Ltd.

Narashingapur, Ashulia, Dhaka-1341

(23.931157N, 90.304182E)

3rd June 2018





Observations



No Drawings for Dining Shed

Observations: Dining Shed



As-built Structural and Architectural drawings were not available at the time of inspection. Building Engineer to survey as-built structure and prepare an “as constructed” drawings (both for RC and steel part) which reflect the actual site dimensions with complete structural information.



Inside Dining shed



Truss connection with RC column

Observations: Factory Building



Problems Observed

Dining Shed:

Item-1: No Drawings for Dining Shed.



Item No.	Observation	Recommended Action Plan	Recommended Timeline
1	(Dining Shed) No Drawings for Dining Shed	Building Engineer to survey as-built structure and prepare an “as constructed” drawings reflecting the actual site dimensions with complete structural information.	6-weeks