

INITIAL FIRE SAFETY INSPECTION REPORT

Cosmopolitan Industries PVT Ltd (Epic) New Shed

RSC ID: 24046

Khejurbagan, Baro Ashulia, Ashulia

23.89259860188969, 90.32353585454244

Other Factories: Cosmopolitan Industries PVT Ltd (Epic) (In the premises)



Inspected By: Pantha Pallob Das & Md.Anisuzzaman

Date:09-Dec-2020

Fire Safety Inspection Report

Cosmopolitan Industries PVT Ltd (Epic) New Shed

Summary:

Cosmopolitan Industries PVT Ltd (Epic) New Shed complex was surveyed for fire safety on 09/12/2020 by The RSC Inspection Team. The purpose of the survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the Accord. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections. Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the RSC for approval.

Findings & Recommendations :

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue. An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the RSC for approval.

Table-1:

SI No.	Category	Findings	Required Action	Remediation Time Frame
F-01	Fire Detection and Alarm System	The fire alarm system installation requires detailed review to confirm compliance with NFPA 72 and ACCORD Standard.	Submit as-built drawings, testing records, equipment certification and other relevant documentation to the RSC for review and approval/acceptance test.	Within 3 months



F-2	Fire Protection System (Standpipe System)	The Standpipe system installation requires detailed review to confirm compliance with NFPA 14 and ACCORD Standard.	Submit as-built drawings, testing records, equipment certification and other relevant documentation to the RSC for review and approval/acceptance test.	Within 3 months
-----	---	--	---	-----------------

